ANDERSON, ECKSTEIN AND WESTRICK, INC.

51301 Schoenherr Road, Shelby Township, Michigan 48315 Civil Engineers • Surveyors • Architects 586-726-1234

2011 Remonumentation Corner: PC-024: Northwest Corner of PC 625

Index

l.	Sectio	n 1
	A.	Index
	B.	Photographs
II.	Sectio	n 2
	Α.	LCRC
	B.	Surveyor's Report
	C.	Analysis of Errors of Original Survey
III.	Sectio	n 3
	Α.	Field Notes
		Corner Witnesses
		2. GPS Notes
		3. Sketch
	B.	Composites
		1. 14-10E
		2. 14-10F
	C.	Correspondence
		Email from Jack Owens RE: record discrepancy
IV.	Sectio	n 4
	A.	GLO Notes and Plats
		1. 1810 Private Claim Description – Greeley
		2. 1810 Private Claim Notes - Greeley
		3. 1817 Township Plat – Preston
		4. 1817 GLO Notes
	B.	Plats
		1. 1920 Mack Avenue Farms No.1 Subdivision – Walter Lehner
		2. 1924 Roseville Gardens Subdivision – Walter Lehner
		3. 1930 Assessor's Plat No. 24 – Walter Lehner

1955 Assessors Plat 60

MCPEDD Tax Map

C.

Misc

RECD MACOMB CO *11DEC15AMO852

PROPERTY OF THE PROPERTY OF

Bulgarage Land

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

_		
-or	corners	10
1 01	COLLEGE	111

(County)	Located In: City of St. Clair Shores	Corner Code # PC 024
1. Public Land Survey	T 1N R 13E T R T R	
 Property Controlling In Section Miscellaneous Property in Sec. 		

1237201 LIBER 21034 PAGE 781 12/15/2011 09:05:49 A.E. MACOME COUNTY, MI SEAL CARMELLA SABAUGH, REGISTER OF DEEDS

Register of Deeds Stamp & File Number

····T

1/22/2017

- 4. Lot No. , Recorded Plat
- 5. Private Claims Northwest Corner of PC 625

Craig P. Amey in a field survey on July 30, 2011 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

2 — (t 3 —	5) (5		3 + 3 - 3
ž —(10
	8 17	(16)	15
8 —(i	9) (20	21)	
10 —(3 1 1 ——	0) 28	28	A.m.
12 —(3 13 ——	1) -3:		

IIII

Item	Date	L	Р	Document	Name	#	Cor. Desc.
1	1810			Private Claim Description	Greeley		Post
2	1810			Private Claim Notes	Greeley		Post
3	1817			Township Plat	Preston	40 Sp. No. 40	Not Indicated
4	1920	4	55	Mack Avenue Farms No. 1 Sub.	Lehner	123	Not Indicated
5	1924	7 '	50	Roseville Gardens Subdivision	Lehner	123	Not Indicated
6	1930	15	6	Assessors Plat No. 24	Lehner	123	Not Indicated
7	1955	32	49	Assessors Plat No. 60	Bridges	5779	Not Indicated
8	2011			MCPEDD Tax Map			

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A research of the public records and a request sent to all area surveyors provided no recorded surveys that reference this corner. The only plat that dimensions this location is Mack Avenue Farms No 1 Subdivision, as recorded in Liber 4 of Plats, Page 55, Macomb County Records (Figure 1). The plat clearly shows the corner to be north of north line of Section 15 (centerline of Champaigne, as shown is the north line of Section 15). According to the GLO Township Plat this corner should be south of the northerly section 15. The GLO notes also do not show the Private Claim line intersecting the northerly line. After reviewing the notes, the township plat, and having discussions with other surveyors, I believe that the section was improperly surveyed by inadvertently omitting calls to the intersection of the west line and north line of section 15 with PC 625. (Cont on back)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 4" x 36" concrete monument with embedded aluminum cap, stamped "MACOMB COUNTY MONUMENT MI ACT 345", "PC—024 REF. PT.", "34970" set in grass of parkway between the sidewalk and the back of curb of westbound 12 Mile Road, 100.00 feet southwesterly from the northwesterly corner of PC 625 (PC-024).

Az 23° 91.61 Sw corner of Mobile gas station. Az 136° Center of top of hydrant on the south side of 12 Mile Road, East of Little Mack 96.71 Az 267° 44.32 Set CST nail w/tag #34970 in north face of utility pole w/camera at northeast corner of 12 Mile Road and Little Mack Avenue. Az 312º Set a chiseled "X" in southeast corner of concrete base for Mobile" sign 23.33'

E OF MICHIGA CRAIG P. **AMEY PROFESSIONAL** SURVEYOR 349, 349, 349, 349, 349,

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THIS CORNER.

Signed by Surveyor's Michigan License No.

DEC 09, 2011

ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN

PUBLIC ACT 345 OF 1990 AT A MEETANG APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 ON 11-2-2011 Martin C. Dum

Revised May 14, 1975 Revised Jan., 1983 Revised Oct., 1995

Liber 21034 Page 782

For corners in

Macomb (County)	_ Located In: City of St. Clair Shores	Corner Code # PC 024
1. Public Land Survey	T 1N R 13E T R T R	
2. Property Controlling	STR	
In Section 3. Miscellaneous	s R	-
Property in Sec.	S T R	

4. Lot No. ______, Recorded Plat

5. Private Claims Northwest Corner of PC 625


B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(Cont. from front) In 1818, William Preston, Deputy Surveyor, surveyed Town 1 North, Range 13 East. Section 15 is a fractional section, and therefore did not follow the normal sequence of subdividing a section as set forth in the 1815 Instructions, issued by Edward Tiffen, Surveyor General. As a result, the west line of Section 15 was the first line surveyed and it was surveyed from North to South, as shown on page 234 of the GLO notes. On Page 239, Preston surveyed the north line of Section 15 by running a random line and correcting back. Any reference to a Private Claim was also omitted from this line. Also on Page 239, Preston surveys the east line of Section 15. As he is running this line, he notes the Private Claims. I believe that at this point, Preston realized his error and attempted to correct his error. It is clear, based on calculations using Preston's dimensions, that this corner does fall northerly of the north line of section 15, as shown on Mack Avenue Farms No.1 Subdivision.

Therefore, I used the dimensions from Mack Avenue Farms No.1 Subdivision to set the location of this corner relative to the section lines of Section 15.

The corner position cannot be monumented because it falls within a structure (currently a gas station). An alternate location along the northerly or westerly line of PC 625 at the right of way of 12 Mile Road also was not suitable due to asphalt paving. We opted to set the monument along the westerly right of way line of PC 625 in the grassy parkway between the sidewalk and curb of westbound 12 Mile Road.

Distance Comparisons	GLO	AEW	Diff
	23.00ch (1518.00')	1514.10	3.90
Nwly cor of PC 625 (PC-024) to int of E line of Sec 15 with Nly line of PC 625 (PCC-025)	80.56ch (5316.96')	5588.94	167.87



ANDERSON, ECKSTEIN AND WESTRICK, INC.

51301 Schoenherr Road, Shelby Township, Michigan 48315 Civil Engineers • Surveyors • Architects 586-726-1234

2011 Remonumentation Corner: PC-024: Northwest Corner of PC 625

Surveyor's Report

PC-024 is the Northwest corner of Private Claim 625 (PC 625). On January 4th, 1810, Aaron Greeley, "Surveyor of Private Claims", filed a description of his survey of PC 625. In his description, he references this corner by citing "to a post". We have been contracted by Macomb County to locate and, if necessary, remonument this position defined by Mr. Greeley.

A research of the public records and a request sent to all area surveyors provided no recorded surveys that reference this corner. The only plat that dimensions this location is Mack Avenue Farms No 1 Subdivision, as recorded in Liber 4 of Plats, Page 55, Macomb County Records (Figure 1). The plat clearly shows the corner to be north of north line of Section 15 (centerline of Champaigne, as shown is the north line of Section 15). According to the GLO Township




Figure 1: Mack Avenue Farms No 1

Plat this corner should be south of the northerly section 15. The GLO notes also do

not show the Private Claim line intersecting the northerly line. After reviewing the notes, the township plat, and having discussions with other surveyors, I believe that the section was improperly surveyed by inadvertently omitting calls to the intersection of the west line and north line of section 15 with PC 625.

In 1818, William Preston, Deputy Surveyor, surveyed Town 1 North, Range 13 East. Section 15 is a fractional section, and therefore did not follow the normal sequence of subdividing a section as set forth in the 1815 Instructions, issued by Edward Tiffen, Surveyor General. As a result, the west line of Section 15 was the first line surveyed and it was surveyed from North to South, as shown on page 234 of the GLO notes. On Page 239, Preston surveyed the north line of Section 15 by running a random line and correcting back. Any reference to a Private Claim was also omitted from this line. Also on Page 239, Preston surveys the east line of Section 15. As he is running this line, he notes the Private Claims. I believe that at this point, Preston realized his error and attempted to correct his error. It is clear, based on calculations using Prestons's dimensions, that this corner does fall northerly of the north line of section 15, as shown on Mack Avenue Farms No.1 Subdivision.

Therefore, I used the dimensions from Mack Avenue Farms No.1 Subdivision to set the location of this corner relative to the section lines of Section 15.

Distance Comparisons	GLO	Adjusted	AEW	Diff
Nwly cor of PC 625 (PC-024) to	23.00 (1518.00)	1518.00	1514.10	3.90
Swly cor of PC 625 (PC-023)	, , , ,			
Nwly cor of PC 625 (PC-024) to int	80.56 (5316.96)	5421.07	5588.94	167.87
of E line of Sec 15 with Nly line of	, , ,			
PC 625 (PCC-025)				

I believe that the method described above has determined the best location of the Northwest Corner of PC 625 (PC-024).

Respectfully Submitted,

Craig P. Amey, PS

ANDERSON, ECKSTEIN AND WESTRICK, INC.

51301 Schoenherr Road, Shelby Township, Michigan 48315 Civil Engineers • Surveyors • Architects 586-726-1234

2011 Macomb County Remonumentation
Analysis of Original Survey Errors
of
Private Claim 625 and Section 15

Private Claim 625 and Section 15 Town 1 North, Range 13 East, Macomb County, Michigan.

Anderson, Eckstein and Westrick, Inc, was contracted by Macomb County to perform remonumentation surveys of Private Claim 625 (PC 625). Corners were to be reestablished at the northwest corner of PC 625, the southwest corner of PC 625, the intersection of the east line of Section 15 with the northerly and southerly lines of PC 625, and the intersection of the northerly and southerly lines of PC 625 with Lake St. Clair.

Prior to conducting our survey, we conducted the necessary research to obtain copies of any prior surveys in the area to assist us with our survey. No prior surveys were found.

Then we obtained a copy of a description of PC 625 by Aaron Greeley, Surveyor of Private Claims, dated January 4th, 1810. The PC is described as follows:

Commencing at a post standing on the border of Lake St. Clair

Thence north 75 degrees west 119.64 chains to a post

Thence north 15 degrees east 23 chains to a post

Thence south 75 degrees east 116 chains to a post standing on the border of Lake St. Clair

Thence along the border of said lake south 6 degrees west 23.28 chains to the place of beginning.

Containing 278.98 acres.

In 1818, William Preston, Deputy Surveyor, performed the original survey of T1N, R13E. Due to Lake St. Clair's position, the township is a fractional township, and therefore the sequential order of the subdivision of the township was not according to the 1815 Instructions issued by Edward Tiffin. Instead of beginning at the southeast corner of the township and then progressing west and north, Preston began at the northeast corner and then proceeded to the south and the east.

When Preston reached section 15, he first surveyed the west line of section 15, starting at the northwest corner of section 15. As he surveyed the west line of section 15, no calls were made as he crossed PC 625. However there are notes immediately following the survey of the west line of section 15 calling out the locations of the intersection of PC 625 with the westerly line of section 15.

The northerly line of section 15 was surveyed beginning at the northeast corner of section 15, running a random line to the previously set northwest corner of section 15, and then correcting back. Similar to the westerly line of section 15, no calls were made as Preston crossed PC 625.

Preston then surveyed the east line of section 15, and along this line, Preston did call out the intersections of the northerly and southerly lines of PC 625 as they intersected the easterly line of section 15.

It is my belief that at this time, Preston realized his error of not calling out the intersection of PC 625 as it intersected the other lines of section 15. There is a note added immediately following the running of the west line of section 15 that states:

"This claim was not observed in Running the sectional when the first notes were made"



It is my opinion that Preston resurveyed a portion of the west line of section 15 to correct his error and call out the intersection of PC 625 with the west line of section 15.

Preston not only erred in the running of the westerly line of PC 625, but it is apparent that he made the similar error on the north line of section 15. PC 625 not only intersects the westerly line of section 15, but according to Preston's own notes, PC 625 must intersect the northerly line of section 15.

While resurveying the westerly line of section 15, Preston intersected the westerly line of PC 625 at a distance of 4.24 chains. At this point, Preston states:

"Int private claim No 625 confirmed to Pirse Duchensia 506 South of the N.W. Cor theirof [sic]"

The dimension "506" is unclear in the notes. It appears to be "5.06" on the face of the township

plat (Figure 1). It is my assumption, based on my experience working with GLO plats, that this distance must be 5.06 chains. That would be the same unit of measurement used immediately following this entry when Preston notes:

"Left the claim 5.96 fom [sic] the S.W. Cor."

I also confirmed this dimension by using Preston's dimensions to establish a position for southwest corner of PC



Figure 1: T1N, R13E, 1818 Township Plat

625. There is no other measurement or units using "506", other than 5.06 chains, that mathematically establishes the southwest corner of PC 625 in a position that is an agreement with the township plat and subsequent monumentation.

By establishing the southwest corner of PC 625, and extending the westerly line of PC 625 from the southwest corner of PC 625 northeasterly through the point of intersection of the westerly line of PC 625 with the section line for a distance of 23 chains, as reported by Greeley, or 23.61 chains as shown on the plat, the position for the northwest corner of PC 625 is at least 2.35 chains *north* of the northerly line of section 15.

This position, located northerly of the section line, is also confirmed by the 1920 plat of Mack




Figure 2: Mack Avenue Farms No 1

Avenue Farms No1, as recorded in Liber 4 of Plats, Page 55, Macomb County Records. The plat title includes the reference "and part of P.C. 625". Furthermore, the plat dimensions the actual location of the northwest corner of PC 625 (Figure 2). In the figure, the corner is shown 155.00 feet northerly of the southeast corner of section 9. This distance agrees within 6 links of Greeley's distance along the westerly line of PC 625 (23 chains record, 23.055 chains measured). The township plat indicates that the distance along the west

line of PC 625 is "23.61" chains which would push the corner an additional forty feet to the northeast. Therefore, it has to be concluded that the correct position is north of the north line of section 15. Had Preston correctly reestablished the position of the northwesterly corner or PC 625, he would have been required to set additional monumentation along the north line of section 15 at the intersection of the section line with the westerly and northerly lines of PC 625 as shown in Figure 2.



As mentioned, Figure 1 shows a distance in chains along the westerly line of PC 625 of "23.61". Greeley's distance, as stated, is 23 chains. Why is there such a difference? When analyzing the section line distances measured by Preston as compared to the same lines measured today, I found the following comparisons:

Line	Preston (ch)	Preston (ft)	AEW (ft)	<u>Diff</u>
Westerly line of section 15	80.00 ch	5280.00	5385.31	+105.31
Northerly line of section 15	80.04 ch	5282.64	5383.12	+100.48
Easterly line of section 15	80.00 ch	5280.00	5128.01	- 151.99
Southerly line of section 15	80.10 ch	5286.60	5391.17	+104.57

The easterly line of section 15 was surveyed shortly after the northerly line of section 15 and immediately prior to the southerly line of section 15. Therefore, any errors with the chain should have been apparent in the northerly and southerly lines. I must assume the discrepancy must be attributed to another source.

It is my observation that the first section line on which Preston calls for the intersection of the Private Claim boundaries, is the same line that is not in conformance with the rest of the lines. There is no evidence that can explain this inconsistency. However, it appears that the majority of Preston's measurements related to the Private Claim are incorrect. Speculation could lead to the conclusion that Preston may have had others survey the Private Claim lines that he had overlooked when first running the section lines. Whatever the reason, it is my opinion that the Private Claim line dimensions from Preston cannot be trusted.

As indicated in the above table, the easterly line of section 15 seems to be inconsistent with the other section lines. In determining the positions of the intersection the easterly line of section 15 with the northerly and southerly line of PC 625, I did try to determine the source or location of the error.

The southerly line of PC 625 was defined by locating monuments in Bay View Subdivision, as recorded in Liber 4 of Plats, Page 55, Macomb County Records. The southerly line of Bay View Subdivision is indicated to also be the southerly line of PC 625.

The northerly line of PC 625 cannot be reestablished from existing monumentation. None of the plats or surveys in the area dimensions its location. Since the original intent of the Private Claim was to have parallel bearings, I extended the northerly line of PC 625 from the northwest corner of PC 625, as established by Mack Avenue Farms No. 1, along a bearing parallel to the southerly line of PC 625 to the easterly line of section 15.

The resulting distances along the easterly line of section 15 to the northerly and easterly lines of PC 625 are as follows:

Distance along the east line of sec. 15	GLO	Adjusted	AEW	Diff
NE corner of sec 15 to nly line of PC 625	29.68 (1958.88')	1997.24	1699.87	-297.37
Nly line of PC 625 to sly line of PC 625	22.92 (1512.72')	1542.34	1615.78	73.44
Sly line of PC 625 to se corner of sec. 15	27.40 (1808.40')	1843.81	1812.36	-31.45

By comparing the distances, it is apparent that there may have been some chaining error between the northeast corner of section 15 and the northerly line of PC 625. Coincidentally, 297 feet is exactly 9 half chains.

After a thorough consideration of the available information, I believe I can safely conclude that the dimensions of PC 625 as described by Aaron Greeley are correct. I also believe that the conclusions support the reestablished positions of the corners and lines of PC 625.

Respectfully Subm	iitted.
-------------------	---------

Craig P. Amey, PS

3005

478 THE TOTAL ME TO LEST A STANDARD WE WANTED THE TOTAL WORLD WE WANTED THE TOTAL WORLD WORLD WANTED THE TOTAL WORLD WORLD WANTED THE TOTAL WORLD WANTED THE TOT

12 Mas 18 2 M Sall S.

FI No OW # 29251 M LOUNCE FI ST OF " INDONE MICONFUL


FE MM CORPT 29 265 11 200

FRITTE NO PLANT M.

FND S/D PRE ALTER MAIL.

11-12 MIN 30 30 30


3005 2611 REMON






COPYRIGHT 2001
MACOMB COUNTY, MI
All Rights Reserved











HARRICH CENTER PER

COPYRIGHT 2001
MACOMB COUNTY, MI
All Rights Reserved

SIS MACOMB COUNTY
Planning and Economic
Development Department

Published: Mar 14, 2007

Re:

From: Jack Owens <jnowenspls@gmail.com>_

To: Craig Amey <cpa34970@att.net>

Mon, June 27, 2011 11:13:58 PM

Yes, very interesting. The PCs were recognized by the US as prior claims to be honored. They took testimony (according to Prof. Berry) as to the persons making the claims and where they were located. Then Greeley surveyed them to define their actual locations on the ground. The surveys were to define them as being the limits of the public lands at least as much as being the parcels. Since it was after the 1796 Act, Greeley should have been surveying according to the true meridian. As Mansfield was the SG, he was very knowledgeable about Astronomy; he would have had them use the true meridian. The GLO Instructions book (Berry's book) has Mansfield's instructions to Greeley which should indicate using the true meridian. Thus, Greeley's survey is the official survey. Therefore, Preston was making retracements of the PC

instructions to Greeley which should indicate using the flue mention. Thus, Greeley a surveys.

Based on your sequence of survey for the lines, which match the records along the PCs of going the Twps laid out from west to east, the lines may not have been that obvious. Also possible that for the east line of Sec15 the owner came out to tell him he was on the PC. Didn't Preston give a measurement to NW cor of PC along n. line? Perhaps the chaining crew made the measurement without preston being with them and said nothing to him about crossing the n. line of Sec15? Based on your info, I'd say any subsequent evidence of the location of lines of the PC is important. I don't know how well Greeley made his measurements. If he did reasonably well, then the difference you see could mean Preston didn't retrace it very well or others subsequently did not? Call Amy Miller at Wayne Co ROD and ask her how well the PCs in Detroit have retraced against the GLO Greeley record. They have been doing them for remon in Wayne Co. and they're all Greeley's work. Preston may not have retraced the PC very carefully and used evidence that was not the survey? But this was only 10 years later so you would think he could see some evidence?

Jack

On Mon, Jun 27, 2011 at 6:45 PM, Craig Amey < cpa34970@att.net> wrote:

Waterford was a good weekend. Butch and I were busy both days. Slow on Sunday morning as usual, but good the rest of the time.

We are thinking along the same lines. I have done some of the calculations you mentioned already. Unfortunately, I need more field information to complete the cales.

Let me ask you a related question. The description by Aaron Greeley does not match the description shown on the twp plat. The bearings vary by about 4 degrees and the distances differ by 60 links or so. So which would be the official record of the PC? Greeleys description or Preston's plat?

I had a different perception of what may have transpired with the survey crew. The chronological sequence of notes has Preston surveying the section line between 15 and 16 without noting the private claim. He then surveyed the north line, also not observing the private claim. Then, when he was surveying the line common to 14 and 15, he notes the private claim. I wonder if at that point preston realized that he had missed the private claim lines, indicating that the private claim lines were not clearly marked. When he realized his error, he went to the line between 15 and 16 to note the intersections, but never did the same along the north line, assuming that the pc did not intersect the north line.

My preliminary calculations show two things: The private claim dimensions per preston don't appear to fit very well, and the NW corner appears to be north of the north section line according to preston's dimensions.

An interesting quandary. Cool!

Craig.

From: Jack Owens [mailto:<u>inowenspls@gmail.com]</u> Sent: Sunday, June 26, 2011 10:05 PM To: Craig Amey, Craig Amey Subject:

Craig.

hope the re-enactment went well. Weather seemed good up here and down there I assume.

Please send me the email addresses for the two attendees. I have some info to send them later in the week.

In regards to your remon project, pass this on if you think it would be helpful.

I would suggest you test the GLO record against itself since the GLO plat and the tax record don't agree on the relative location of the 'NW cor' of the PC. You could draw (in CAD) both the section and the PC and see how they 'fit' per record dimensions. By this I mean draw the section with N-S lines due north and 80 chains long (convert to equivalent feet for the record distances). Draw the north line due west at the record width. Draw the south line in and adjust it to be the record widt bh, slightly adjusting the east or west line to fit that width. On the east line make a short reference line at the two record stationings for the 'N' and 'S' lines of the PC, calling them points A and B. On the west line make a short reference line at the record stationings for the 'W' and 'S' lines of the PC, calling them points C and D. From this you can connect points B and D on the 'S' line (with a dashed line) and compute the bearing of the 'S' line of the PC. That can be compared to the bearing for it by Greeley. Both Preston and Greeley were supposedly running lines according to the true meridian. However the two bearings compare will give you some info, that may or may not be useful.

Greeley. Both Preston and Greeley were supposedly running lines according to the true meridian. However the two bearings compare will give you some into, that may or may not be useful.

Next draw the PC according to the record bearings and distances. From the 'NW' corner draw a reference line on the 'N' line at the record 80.56(?) chains E'ly of the NW corner, calling it point A1. Make a copy of this figure; then make a block of it. Move the block, using point A1as the insertion point, to the section figure, inserting it at point A on the east line of the section. Next rotate the block around the coincidence points A and A1 until the south line of the PC is on points B and D on the east and west section lines, or looks to be parallel with them. This will show whether the 'NW' corner falls south of the north line of the section, or north of it. This will at least give you a feel for how well the two survey records report the actual conditions.

We know Preston saw evidence for the PC lines gong south on the east line of the section. He measured along the north line of the PC, so it must have been clear enough to follow, and he seems to be stating the NW cor was there and seen by him. He ran the west line and then notes he went back to get the stationings for where it crossed the W and S lines of the PC. To me this indicates he may not have been with the chaining crew on the west line of the section and had to send them back to get the measurements. He ran the north line of the section and does not report crossing the lines of the PC near the NW cor of the PC. Thus, it seems reasonable to conclude he did not cross it.

You might also try retracing the east and west section lines and putting in the N and S line crossings of the PC by proportionate position. This would let you establish the S line and at least a point on the N line by which to compare to other info about reported positions along the lines of the PC. Very interesting remon project.

No. 87

No. 625 Confirmed to Pierre Duchesne

LAKE ST. CLAIR


Description No. 625 Confirmed to Piere Duchane commencing at a post standing on the border of Lake St. Clair between this tract and unconceded land thence north seventy five degrees west one hundred and nineteen chains sixty four links to a post thence north fifteen degrees east twenty three chains to a post thence south seventy five degrees east one hundred and sixteen chains to a post standing on the border of Lake St. Clair between this tract and a tract of unconceded lands, thence along the border of said lake south six degrees west twenty three chains twenty eight links to the place of beginning, containing two hundred and seventy acres and ninety eight hundredths of an acre,


Detroit Jany 4th, 1810

Aeron Greeley Surveyor of private claims

N.87. Lake St. Blair Description N. 625 confirmed to Rum Duc! ane, commencing at a post stand. ing on the border of Jake It Blain between this track and unconceded land, thener north seventy five degrees west one hundre and windless chains tryly four links to a post thence north fifteen degrees east twenty three chains to a post thence south seventy five degrees cast one hundred and sixteen chains, to a post standing on the border of Sake of Clair between this track and a track of unconceded lands, thence along the Border of sand take worth six degrees west twenty three chains twenty eight links, to the place of begin sning containing two hundred and sevcity acres, and winety eight hundred the of an acre Detroit January 4 1810 Auron Greeley Herveyor

4.4.1





40,00 Mile Walf mile Co un on a W. Cak le su di 411.17 a B. ash 16 in di 10,00 Set post yes Section 16.15:22,21 in Which a B. Oak 14 midi bears & S. 5 & 11 lun also a 13. ach 16 in di becare N'30 W 25 links 1. half mile level and wet 2d rate last bull mile same Timber B. ash Beech Elew Lynn + Undergrowth Lynn B. Och to 1124 Ent private claim Nº 625 Confirmed to Perse Incherin 50.6. South of the N.W. Con theirof Made Cer. for frao sects 15416 on our ash & in clean East 22,01 Left the claim 5,96 four the S.W. Con thereof made Cor for pac. Dec 15.16 a: B. ash 14 in deam 3 This claim was not observed in Running the sectional solven the fact notes were made West Ou Randow between S. 16+21 40,00 Set tempy half mile front 80,20 But West beneday 15 link South of conur Land level Part dry 2. nate Timber B. ash Beech Sugar Lynn Undergrowth Spice + c East Com between 16+21 4010 Madely section comer on a B. ash 7 sie dia at average distance Tru lieu 8020 To Section comes

10.00 Set host for section. 10.11-14.15 from Which a Beech 14 in di beare N 23 6 Thinks also a Buch bin dia bears NG5 W 6 links cliet fullall mile good 2th rate Simber W.Oak Buch Sugar v. West Ou Roudan between 5.10 +15 11000 Set level half mile for 80,04 Buld West boundy atthe Comer Land level Part dry 2th pale Finder Buch Elul to Gast Corrected between 10415 40.02 Made 14 Section Corner on a Beach 4 m di at average dietance 80,04 To Section Corner East Between Sections 11+14 38.37 Inter Lake St Clair and Set frost for fracul sections 11414 from Which & Sycamore 18 sin di bears N 37 & 33 links also a Maple 12m bears 847 W45 littles diet Tam past ony 2t rate Timber Buch B. ash Elm ye South Between Sections 14+15 5:00 a B. ash 18, m dia 29.68 Interes Prot claim 80.56 from N.W. comes of Lot Nº 6.25 and Made Comer on an Bronwood 4 ins dia for fad sect 14 +15=32.60 lift 144

the Lain and mai conur for fract Sections 14+15 Buch 12 N 71 & 19 Do. 158 m15 80.00 Set post, for fract Sections 4.15:22.23 from which ten Elen 24 m di bear NUII é 11 links di also an Elm 22 m di bears 824613 lunks dist Part dry 2" rate terriber Beach Elm East Between Sections 14 423 3.50 Enter a Praisi 25.08 Int Lake St Clair and Set front for fraction. Sections 14+23 broke Which a Sycamore 24 m die beare S. 10 W 2,50 also a Balsung Gilliad 30 mi dia bears North 177 links dist Met and marshy 3rd rate West On Randon between Sec. 15+22 4000 Set lemporary poet 80,10 Entersected A+8 line at sec, cor. East On Free line belevan Sect 15-422 40.05 Sety see comes wash 10 84207 Lym 12 N 50 W 12 Generally low not land well tomber B. ask Elin Lynn to 8010 Secr Comer South Between Sections 22+23 4.4.4 40.00 Made 'y Sec Cor on B. ash 6 m diam 45.86 But Private Claim No. 623 confirmed


afril 30-1920

PLAT MACK AVENUE FARMS Nº1 SUBDIVISION"

5. W 4 of S. W. 4 of Sec. 10 and Partoff 625 TINR 13 Erin - Twp Macomb County Michigan.

Scale 200 ft = linch

> Wolter J. Lehner County Engineer MtClemens, Mich.



REGISTER'S OFFICE ... A.D.. 1942 o... at of Irele Notice of Recorded Libra H 55 Christs, 7/ Rubb

Prince for Carthy, that there are no Tax libras or These by the Carter a say, had writed against, and that all Tuses on have dissultant the amoretal instrument have been path FIVE YEARS pitz to the date thereof, apprending by the records of this Office.

A 19 AD County Tustorier, Baconic County, and

DEDICATION.

and Michigan Taxest ment Company by Richard G. Lambrecht, Providen and Carl Wisner Secretary, as proprietors,

AND PLATTED, TO BE KNOWN AS MACK AVENUE FARMS NO. 1. SUBDIVISION, S.W. OF S.W. . 3 OF SEC. 10. AND PART OF 675 T.I.N.R. 13E. LAKE TOWNSHIP, MACCOMB COUNTY, MICHIGAN. AND THAT THE STREFTS AND ALLEYS AS SHOWN ON SAID PLAT ARE HEREBY DEPICATED TO THE SUSTED OF THE PUBLIC.

SIGNED AND SEALED IN PRESENCE OF James In Management

SIGNED AND SEALED IN PRESENCE OF Chasique

STATE OF MICHIGAN.) SS. COUNTY OF WAYNE

Whigh inespects company Edward L. Coppas. by CASA MASTER

THE ABOVE DEDICATION, AND ACKNOWLEDGED THE SAME TO BE THEIR FREE ACT AND DEED. also

ON THIS --- 54 DAY OF BEST A.D. 1920, BEFORE A NOTARY PUBLIC IN AND FOR SAID COUNTY APPEARED GENERAL Santosthy Good Munic TO ME PERSONALLY KNOWN, WHO BEING EACH BY WE DULY SHORN DID SAY THAT THEY ARE THE PRESIDENT AND SECRETARY RESPECTIVELY OF THE SEAL OF CORPORATION, AND THAT THE SEAL AFFIXED TO SAID INSTRUMENT IS THE CORPORATE SEAL OF SAID CORFORATION AND THAT SAID INSTRUMENT WAS SIGNED AND SEALED IN BEHALF OF SAID CORPORATION BY AUTHORITY OF ITS BOARD OF DIRECTORS AND THE SAI HELSAND I Lamberth & Carl Mus

Resolution, Lide 3168 B. 148 MY COMMISSION EXPIRES - Cart 1511982

I HEREB CERTIFY THAT THE PLAT MEREON DELINEATED IS A CORRECTION AND THAT PERMANENT MONUMENTS, CONSISTING OF 3 & GALVANIZED PIPE 16: LONG, HAVE BEEN PLANTED AT POINTS MARKED THUS (0) AS THERON SHOWN AT ALL ANGLES IN THE BOUNDARIES OF THE LAND FLATTED, AND AT ALL INTERSECT

Males SURVEYOR Way stend com a

CERTIFICATE OF MUNICIPAL APPROVAL.

THIS PLAT WAS APPROVED BY THE TOWNSHIP BOARD OF THE TOWNSHIP OF ELLO Very Juil CLARK.

> Description of Land Platted aced in the annexed Plat of MACM. ENRMS de l'Entedistrian, SW Heat SW Jack Sec Ja and part of RL625 THATISE Lein Tap Maconth Lands Michigan
> is described as follows: Beginning at the SE Con of See 9
> End Tup thence NOS: 12:00 E 13:190 Ft; thence NUTTON W
> 13877 Ft; thence SOS: 37:30 W 134189 Ft; thence SOSG-30 E
> 13325 Ft. It the place of beginning.

his plat was approved by the County Board for Haconical County, Michigan, st. a moeting held. Judge of Probal ...Judge of Probabe, M. Manuacas T. L. Lander Com

Lu coment L. 1881 8.594 sin coment L. 1881 8.595 he coment L. 1811 P. 596 mur 3-1924 ROSEVILLE GARDENS SUBDIVISION OF THE SE 4 OF THE ME 4 OF FR'L SECTION 16 TIM. RIJE LAKE TWP MACOMB CO. MICH. D 0. 50 WALTER J.LEHNER. REGCE MTCLEMENS MICHIGAN /85 /86 /87 /88 60 , have caused the land embraced in the annexed for the royse, laid out and platted, to be known as floorville Gardens Subdn. of the NE 4 of Frt. section 16 TIN. RISE Lake Two Maromb Co Mich. and alleys as shown on said that are of the public. of the Stanly L. Woman L.S. Jeanette Wornick . 45 Joseph Beste ... Mary Beste ...

This is to certify that the above plat was approved by the ship Board of the Township of

Scoomb County, Michigan, at a meeting held this 7 day of august 1983

State of Michigan County of Milistery John of Lease 1923.

On this Jaine Holary Public in and for earl County, personally came the above named faceth Heighter Filling his north from the January has write from to me to be the persons who executed the above dedication, and acknowledged the same to be the persons.

I result John Mary Mich Co., Bich.

My Commission Expires a Latelan 18 18 1926

The 19 192 4-COUNTY OF MACOUR ged in the appeared Plat of Roseville Gardens


i er filfir og

Subdivision of the SE 4 of the NE 14 of Fr 1. Sec. 16 TIN, RISE Lake Tryp. Macomb Co. Mich.
is described as follows: Beginning at the E4 corner of said Sec.16, Thence N89°53'W, 1344.0 ft., thence NO°28'W. 1344.44 Ft. thence \$89°46'E 1175.1 Ft. thence \$69°45'E 183.09 Ft., thence \$0°22'E 1279.1 Ft. to point of beginning.

I hereby certify that the plat hereon Dolineated is a correct one and that permanent monuments consisting of ½ x 18 inch from Stakes have been planted at points marked " " as thereon shown at all angles in the boundaries of the land platted and at all intersections of streets or streets and alleys.

Registered C.E.

Lbu 1031 pa 389 (Part of Lot 27) July 5-1933 SEC.16, FR'L SEC. 15 & F. C. 625 TINR.13,E. SHOKES MACOMB CO. MICH. VILLAGE ST CLAIR TWELVE MILE 23 21 Zo 19 17 15 MACK LITTLE ROSEVILLE Julia Caration Ethe Matter AUS 7. 1930. A.D., 192 whith Warrer STATE OF KICKIGAN COUNTY OF MACOUS Notary Public in en: 10r mae oul. Commission expires Och 78 1432 DESCRIPTION The land embraced in the annexed plat of "Association Fig. Sec. 15, and P.C. 625, T.1, N.H. 13 E. Village of writed as follows: BURVEYORS CERTIFICATE ly 15 1930 Chas T'Dedurick Jacks of Jackson Debat of County Clark.



ASSESSORS PLAT 60

233646

OF PART OF LOTS 12 THRU 23 OF ASSESSORS PLAT NO.24 PARTS OF NE. FRLIASEC. 16, FRL SEC. 15 & P.C. 625 T.IN.,R.I3E.

CITY OF ST. CLAIR SHORES, MACOMB CO., MICHIGAN.

Vista Pargundi

N

88

PAGE

10

35

36 37

38

43

46

47

Note: All dimensions are in feet and decimals thereof.

Scale 1=100' 0 50 100 200

Walter J. Lehner & Sons Reg. Civil Engineers & Surveyors Mt. Clemens, Michigan.

N.87°35' W. 342.41'

N.E. Cor. 546. 16

T.INR.134. TWELVE MILE RD. 120 FT. WIDE 5.67° 35'E. 345.78' DE 345.78' à 23 + 22 3 21

/9 **7**

18

16

15 12 13

/3

12

17 18

21

25 /25. JZ'

N. 87 * 35 '30" W. 302.30"

1/4 GAFFKE AVE. 4 of Cox Drain To be closed with storm sewer).

DEDICATION

KNOW ALL MEN BY MESE FRESENTS, That I, Adrian A. Lingemann, Assessor of the City of St. Clair Shores of Macomb County, State of Michigan, by virtue of authority in me vested by Section 51, Act 172, of 1929, having been duly authorized by the City Council have caused the land described in the annexed plat to be surveyed, leid out and platted, to be known as "Assessors Pist Co of part of Lots 12 thru 23 of Assessors Piet No. 24 of parts of N.E. Friksec. 16, Fri Sec. 15 & P.C. 625, T.IN., R.13E. City of St. Clair Shores, Macomb Co., Michigan, and that the streets as shown on said plat are now being used for such purposes.

Donald J. Harm. Bonard J. HARM. Skind 3 J. Jane ACKNOWLEDOMENT.

ACKNOWLEDGMENT.

STATE OF INICHICAN
COUNTY OF A.D. 1955, before me a Notary Public
in and for seld county, personally came the above named Adrain A. Lingemann,
Assessor of the City of X. Clair Shores, known to me to be the person who
executed the above dedication, and soknowledged the same to be his free act
and dead as such assessor.

My Commyssion expres: 1

Notary Public in and for
Co., Mich.

The land embraced in the annexed plat of Assessors Plat 60 of parts of N.E. Fringsec. 16, Fri Sec. 15, E.F.C. 625, T. 1 N., R. 13 E., City of St. Clair Shores, Lacond County, Minhigan, is described as follows: Commencing at the Northeast corner of said Section 16, T. 1 N., R. 13 E., and thence extending N. 87° -05° W. 342.41 feet; thence S. 2°-36°-08° W. 60.0 feet to the point of beginning of this description; thence extending S. 2°-36'-08° W. 1152.15 feet; thence S. 19°-50° W. 199.80 feet; thence N. 87°-35' -30° W. 302.30 feet; thence N. 2°-36'-08° E. 1285.53 feet; thence S. 87°-35' E. 343.72 feet to the point of beginning.

SURVEYOR'S CERTIFICATE

I hereby certify that the plet hereon delinested is a correct one and that permanent metal monuments consisting of bers not less than one-half inch in diameter and 36 " in length, encased in a concrete cylinder at least 4 inches in diameter and 36" in depth have been placed at points marked thus (0) as the shown at all angles in the boundaries of the land platted, at all the intersections of the lines of streets, and at the intersections of the lines of streets with the boundaries of the plat as shown on said plat.

Fits A practice, its discovery in the plat as shown on said plat.

CERTIFICATED OF LUNICIPAL APPROVAL

This plat was approved by the Common Council of the City of St. Claim Shores, at a meeting held wine 6, 1955

THE A TO CHAIR THE ACCOUNT TO THE COUNTY TROCKNESS TO THE PROPERTY OF THE PARTY SECURITY SECURITY OF THE PARTY SECURITY SECU

Drain Commissioner

REGISTER'S CEPTURE SECURITY OF MACOMB Received for Record. June 24, 1955 at 1/1. 8.0 Octock & M., and recorded in Vol. 32 of Plate, on in vol. 22a

Approved By
City of St. Clair Shores
Planning Commission 197 24 105 27
Register of Design School County Treasurer

Charten South Treasurer

Charten South Treasurer

