2004 MACOMB COUNTY REMONUMENTATION PROGRAM FOR BRUCE TOWNSHIP

Research Dossier for L-6

Prepared by: Kennedy Surveying, Inc. 105 North Washington Street Oxford, Michigan 48371 04-5850 (96-4013)









LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

arasikas urs — ma 3 Partijos — S

For corners in	r mig rode	in cinetic of Aque 1-4, Midile 1.	.A. 1070	1
Macomb	Located In: C	Corner Code # ip		1
(County) 1. Public Land Survey	T 5N R 12E T R T R T R		4160252 LIBER 15653	PAGE 23
2. Property Controlling	s T R			
in Section 3. Miscellaneous Property in Sec.	T R T R S T R S T R S T R		07/14/2004 08:48: MACOMB COUNTY, MI CARMELLA SABAUGH,	23 A.M. SEAL REGISTER OF DEEDS
4. Lot No, Recorde 5. Private Claims	d Plat		ABCDEF	G H I J K L M
		THE STATE OF THE S	2 6 5 4	3 2 1
I, <u>Huston K. Kennedy</u> , in a requirements of P.A. 74, Michigan P.A conformance with regulations and rules United States Department of the Interic that the corner points mentioned in line Board of Land Surveyors or by a D recovered, found as expressed below:	A. of 1970, the corner points mer s therefore as required in the curre or, Bureau of Land Management o es 3, 4 and 5 above were in confor Decree of a Court of Law; esta	ntioned in lines 1 and 2 above we ent manual of survey instructions or or by a decree of a Court of Law a rmance with the rules of the Micl	ore in 5	15 14 (13)
NOTE: Not more than 2 corners on this certificate.	, all in the same town and ran	ge, may be recorded	9	27 26 25
A. Description of original monu 1817-GLO Wampler, D.S	ument and accessories and/o 5.; A post was not set duri	or subsequent restoration: ng the original governmer	12 31 32 33 13 11 32 33	34 35 36
Brown Road extending to	g, Inc. – Kennedy, PS #17 o the North and South, wh	′623 – Fnd a ½″ Iron Rod nich has a bituminous surf	shing corner: in a monument box in the e ace, also 2 feet North of the No line occupation to the Ea	existing center line of
I could not find any record	ded or unrecorded inform	ation to dispute the location	on of this corner.	
I accepted the found 1/2" I	ron Rod as the best evide	ence of the original corner	positon as being perpetuate	ed.
Field measurements betw			10 mm	HUSTON HUSTON
C. Description of monument fo L-6 I replaced the found Monument, MI Act #345, S11°W 125.39' Set Mag I S43°E 90.45' Set Mag N N54°W 43.89' Set Mag N N07°W 189.07' Set Mag I	1 ½" Iron Rod with a ¾" PS #17623 Nail w/washer East face F ail w/washer SW face twir Iail w/washer SE face Poy	' x 24" Iron Rod w/2" dia Power Pole n 14" Birch wer Pole	ing the position of the core ameter aluminum cap	PROFESSIONAL SURVEYOR PROFESSIONAL SURVEY PROFESSI
The selected location is accepted position of the original column	rnor. A	rally accepted by Profess	ional Surveyors as the bes	t available evidence of
Signed by: Surveyor's Michigan License No		Date _	June 2, 2004	
Surveyor's Michigen License No	17623	FORM APPROVED BY MICHIGA	AN STATE BOARD OF PROFESSIONA	L SURVEYOR'S, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995
ACCEPTED BY THE MACOMB CO GROUP AS THE OFFICIAL CORN PUBLIC ACT 345 OF 1990 A ON 29 29 64	IER UNDER MICHIGAN			
MARTIN C. DUNN, P.S.	CHAIRMAN			

Town 5 North, Range 12 East, Bruce Township (L-6)

Section "B" Con't

FIELD MEASURMENTS BETWEEN CORNERS

<u>L-6 to K-6</u>

No GLO S77°35'51" W 2670.36 Ft. (m)

<u>L-6 to L-5</u>

No GLO N03°16'10" W 2703.47 Ft. (m)

<u>L-6 to L-7</u>

No GLO S02°35'40" E 2685.93 Ft. (m)

<u>L-6 to M-6</u>

No GLO N77°07'17" E 2606.37 Ft. (m)

Liber 015653 Pase 00024

Sources of Information Researched For Macomb County 2004 Remonumentation Program For Bruce Township

1) GLO Notes	
2) Act 74 Recorded LCRC	
3) Act 132 Recorded Surveys	
1) Personal History and Records	
5) Unrecorded LCRC's and Surveys	
6) Letters to the Following, Requesting Unrecorded inf	ormation
□ a) AES Engineers & Surveyors, Inc. □ b) Anderson, Eckstein & Westrick □ c) BMJ Engineers & Surveyors □ d) Bruen Land Surveying □ e) David Little Land Surveyor □ f) Dunn Construction □ g) Fenn & Associates Surveying, Inc. □ h) George F. Dely Co, □ l) George Jerome & Company □ j) Kem-Tec Surveying □ k) King Surveying & Associates, Inc. □ l) Lansky Land Surveyor □ m) Lehner Associates, Inc. □ n) M.C.S. Associates, Inc. □ o) Metco Land Sea Corp., □ p) Metco-Dunn, Inc. □ q) Michalich & Associates □ r) Milletics & Associates □ r) Milletics & Associates □ r) RA. Duthler Land Surveyor LLC □ u) Reichert Surveying □ v) Road Commission for Macomb Co □ w) Rowe Incorporate □ x) Spalding, DeDecker & Associates □ y) Urban Land Consultants, L.L.C. □ z) Williams & Gorinac Associates	ounty

GLO NOTES

Researching the government survey records for Macomb County shows that the North & West lines of Bruce Township was surveyed an the township was subdivided into sections with closing corner set on the North & West township lines by Joseph Wampler, D.S. in 1817. A post was not set at the Center of Section 13.

WITNESSES:

(Based upon Government Survey Records)

EXISTING CONDITIONS

A post was not set during the original government survey. The corner has been perpetuated with a $\frac{1}{2}$ " Iron Rod in a monument box in the existing center line of Brown Road extending to the North and South, which has a bituminous surface, also 2 feet North of the existing center line of Ebeling Road extending to the West, which also has a bituminous surface. No line occupation to the East due to the common ownership.

LCRC AND RECORDED SURVEYS

Researching the Macomb County Records for Land Corner Recordation Certificates (LCRC) and Certificates of Surveys shows that nothing has been recorded for this corner.

FIELD MEASURMENTS BETWEEN CORNERS

L-6 to K-6

No GLO S77°35'51" W 2670,36 Ft. (m)

L-6 to L-5

No GLO N03°15'44" W 2702.82 Ft. (m)

L-6 to L-7

No GLO S02°35'40" E 2685.93 Ft. (m)

L-6 to M-6

No GLO N77°07'17" E 2606.37 Ft. (m)

I could not find any recorded or unrecorded information to dispute the location of this corner. I therefore, recommend to the Macomb County Peer Group that they accept the ½" Iron Rod as found as the best evidence of the corner position as being perpetuated.

Huston K. Kennedy, PS

Kennedy Surveying, Inc.

GLO NOTES

Researching the government survey records for Macomb County shows that the North & West lines of Bruce Township was surveyed an the township was subdivided into sections with closing corner set on the North & West township lines by Joseph Wampler, D.S. in 1817. A post was not set at the Center of Section 13.

WITNESSES:

(Based upon Government Survey Records)

EXISTING CONDITIONS

A post was not set during the original government survey. The corner has been perpetuated with a $\frac{1}{2}$ " Iron Rod in a monument box in the existing center line of Brown Road extending to the North and South, which has a bituminous surface, also 2 feet North of the existing center line of Ebeling Road extending to the West, which also has a bituminous surface. No line occupation to the East due to the common ownership.

LCRC AND RECORDED SURVEYS

Researching the Macomb County Records for Land Corner Recordation Certificates (LCRC) and Certificates of Surveys shows that nothing has been recorded for this corner.

FIELD MEASURMENTS BETWEEN CORNERS

L-6 to K-6

No GLO S77°35'51" W 2670.36 Ft. (m)

L-6 to L-5

No GLO N03°16'10" W 2703.47 Ft. (m)

L-6 to L-7

No GLO S02°35'40" E 2685.93 Ft. (m)

L-6 to M-6

No GLO


N77°07'17" E 2606.37 Ft. (m)

I could not find any recorded or unrecorded information to dispute the location of this corner. I therefore, recommend to the Macomb County Peer Group that they accept the 1/2" Iron Rod as found as the best evidence of the corner position as being perpetuated.

Huston K. Kennedy, PS Kennedy Surveying, Inc.

(Revised 6/4/04)





Theoretical Center of Section (the intersection of the 1/4 Section Lines) L-6 (As Found) to the Theoretical Center of Section N64°40'34"W 17.82'


Center of Section that is being accepted and used.

(UR) = Unrecorded


Not To Scale

SECTION 13, T5N,R12E BRUCE TOWNSHIP (96-4013)


4/5











<u> </u>		6–9 to 6–8 GLO=40 Ch		GL0=40 Ch 2770.47(Sur)		N02'5'	c-7 to c-6 GLO=40 Ch 2493.02(Sur) 7'38"W 2493.53	·///	N02'32	G-6 to G-5 GLO=40 Ch 2765.98(Sur) '54"W 2766.	04(M)	×03	GL(206 25'28
N8813'36"E 2677.22(M) 28 (043)	NO2'38'2	H-9 to H-8 No GLO	(030) 0-8 to H-8 (0-8 to H-8 (H-8 to H-7 No GLO 2713.99(Sur) 50'41'W 2714.25	N87'50'42"E 2653.35(M)	©10 GL0=40.41 Ch G-7 2652.95(Sur)	H-7 to H-6 No GLO 2563.25(Sur) 1'19"W 2563.48(M)	N96°20'18"E 2665.45(M)	(013) C-6 to H-6 C-6 No GLO 2865.21(Sur)	H-6 to H-5 No GLO 32'29"W 2662.1	NE33313"E 2665.75		H−5 No 2634 306'5
N874752°E 2643.02(M) (25)	H-9 GL0=40.42 CH	-53 -9 to 1-8 GL0=40 Ch 2655.84(Sur) 15"W 2655.97(N85'46'05'E 2579.17(M)	VAN	488°06'51"E 2647.30(M)	(008) GL0=40.41 Ch H-7 2647.21(Sur)	DYKE GLO=40 Ch 2628.91(Sur) 3'39"W 2628.87	N86'42'07'E 2658.41(M)	1020 H-6 H-6 to 1-6 No GLO 2658.67(Sur)	ROAD -8 to -5 GLO=40 Ch 2580.94(Sur)	N88727'54"E 2660.90(M)	GL0=40.40 Ch 2661.20(Sur)	GLO: 2662 9'36"
-	(019) → 10 ← 9 -9 GLO=40.03 CH -8 2620.69(R) 2621.02(R)	J-9 to J-8 No GLO	(O)8 I-8 No GLO NO GLO NO GLO NO GLO	J−8 to J−7 No GLO '43'38'W 2724.4'	MN867112"E 2688.58(M) N	0.21 Ch 74(Sur)	J-7 to J-6 No GLO 2626.25(Sur) 13'07'50"W 2626.18	N86724'05"E 2657.08(N)		J–6 to J–5 No GLO 2632.51(Sur) 01°59"W 263	N851617E 2833.64(M) (X)	999) -5 to -5 -5 GL0=40.32 Ch 20 2633.12(Sur)	J-5 t No 2667 1'17"
	(049) J-9 to K-9 J-9 GLO-40.03 CH 2695.04(R)	ROAD K-0 to K-0 GLO=40 Ch GLO=40 Ch GLO=40 Ch	054) J-8 1-8 to K-8 No GLO N8745'14"E 2858.31(M)	K-8 to K-7 GL0=40 Ch 2742,34(Sur) 8'02"W 2742.	187'21'22"E 2613.13(M)	(056) GL0=40.21 Ch (-7) 2612.57(Sur)	K-7 to K-6 GLO=40 Ch 2669.87(Sur) 9'29"W 2669.91	(M)	038) Je to K-6 00 00 00 00 00 00 00 00 00 00 00 00 00	K-6 to K-5 GLO=40 Ch 2665.77(Sui 1'37"W 266	5	(055) J-5 to K-5 J-5 GL0=40.32 Ch 2666.87(Sur)	K−5 GLO- 268: 28'19'
	N77736107F 2608.57(N)	03°W 2594.37(NO GLO 806.37(Sur)	3L-8 GLO B(Sur) 264241(N)	NO GLO 2727.00(M)	N7757'07"E 2672.42(M)	(039) K-7 to L-7 GL0=40.20 Ch K-7 2673.27(Sur)	L-7 to L-6 No GLO	N77'35'51"E 2670.36(M)	(03) K-6 to L-6 No GLO 2657.14(Sur)	L-6 to L-5 No GLO	N76°40°48"E 2642.88(M)	(04) K-5 (0 L-5) Ch K-5 GL0=40.35 Ch 2843.18(Sur)	L-5 No
	N7917725°F 2865.90(M)	M-8 to M-9 GLO=40 CH 2666.50 Meas	L-8 No GLO (199) 2645.21(M) M-8 N7744'44"E 2647.25(M)	M-7 to M-8 GLO=40 CH 2732.33 Meas 2732.35(R)	77°28'52"E 2619	(064) L-7 L-7 to M-7 GL0=40.20 Ch) N770717E 2606.37(M)	040 L-6 L-6 to M-6 (178)	M-5 to M-6 GLO=40CH 2700.02 Me	20(E) eas	(072) L-5 to M-5 (236) L-5 GL0=40.35 Ch	M-5 GLO= '44'07
C Map of leas.	2657.2 265 265	A-8 to A-9 NO GLO 22 MCPC Maps 57.42 Megs. 557.60 (R) 10 A-9 8 LKS (R/S)		A-7 to A-8	2752 (B4) A-7	7 26; M-7 GLC 110	A-6 to A-7 NO GLO 71.87 MCPC Map 2671.92 Meas. 2671.87 (R) to A-7 0=1.50 CH .77 (Survey) .77 Meas) (M-6 NO 138.	A-5 to A-6 NO GLO .72 MCPC Mc 13.32 Meas. to A-6 GLO 62 Meas		A-5 GL0 125	A-5 NO 370.18 to M- 0=8 3.58 I