ANDERSON, ECKSTEIN AND WESTRICK, INC.

51301 Schoenherr Road, Shelby Township, Michigan 48315 Civil Engineers • Surveyors • Architects 586-726-1234

2012 Remonumentation

Corner: PCC-030: Intersection of the north line of Section 15 with the northerly line of PC 625.

Index

- I. Section 1
 - A. Index
 - B. Composite
 - C. Photographs
- II. Section 2
 - A. LCRC
 - B. Surveyor's Report
- III. Section 3
 - A. Field Notes
 - 1. Corner Witnesses
 - 2. GPS Notes
 - 3. Sketch
- IV. Section 4
 - A. GLO Notes and Plats
 - 1. 1810 Private Claim Description Greeley
 - 2. 1810 Private Claim Notes Greeley
 - 3. 1817 Township Plat Preston
 - 4. 1817 GLO Notes
 - 5. 1895 Atlas
 - 6. Mack Avenue Farms No. 1
 - 7. Assessor's Plat No. 24
 - B. Original Corner LCRC's
 - 1. G-05 L:6862 P:831
 - 2. H-05 L:19067 P:925
 - 3. PC-024 L:21034 P:781
 - 4. PC-025 L:21051 P:848



16.4 (146

COPYRIGHT 2001
MACOMB COUNTY, MI
All Rights Reserved










MAVEN VILLA




Legend Platted Area Boundary Li Property Line Property Split Line Property Combined Line Township Boundary Line Traverse Line












PCC-030
















LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

T 1N R 13E T R T R
T R

3177220 PAGE 1 DF 1 LIBER 22568 PAGE 805 12/03/2013 03:19:43 P.M. MACOMB COUNTY, NI CARMELLA SABAUGH, REGISTER OF DEEDS

Register of Deeds Stamp & File Number

, Recorded Plat

5. Private Claims Intersection of the North line of Section 15 with the Northerly line of

Craig P. Amey in a field survey on July 12, 2012 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

						13	
ltem	Date	L	Р	Document	Name	#	Cor. Desc.
1	1810		-	Private Claim Description	Greeley		Post
2	1810		***	Private Claim Notes	Private Claim Notes Greeley —		Post
3	1817			Township Plat	Preston		Not Indicated
4	1817		***	GLO Notes	Preston		Not Indicated
5	1895	1444	****	Atlas		•	Not Indicated
6	1920	4	55	Mack Avenue Farms No. 1	Lehner	123	Pipe
7	1930	15	67	Assessor's Plat No. 4	Lehner	123	Not Indicated
7	2011	21034	781	LCRC	Amey	34970	Concrete Monument
8	2011	21051	848	LCRC	Amev	34970	Concrete Monument

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

PCC-030 is Intersection of the North line of Section 15 with the Northerly line of PC 625. A research of the public records and a request sent to all area surveyors provided no recorded surveys that reference this corner. To locate the position, I intersected the northerly line of PC 625 as approved by the Macomb County Peer Review group in 2011 and monumented by corners recorded in Liber 21034, Page 781 MCR and Liber 21051, Page 848, MCR, with the north line of section 15 as defined the northwest corner of section 15, as recorded in Liber 6862, Page 831, MCR, and the north quarter corner of Section 15 as recorded in Liber 19067, Page 925 MCR. The corner location is in the center of 12 Mile Road, a bituminous surface, and is located approximately 0.43' south of the centerline of 12 Mile Road.

Distance Comparisons	GLO	AEW
PCC 030 to northwest cor of PC 625 (PC-024)	None	439.67'
PCC 030 to PCC 025	None	2305.83'
PCC 029 to PCC 030	None	465.70'
PCC 030 to north quarter corner of Section 15	None	2165.51'
PCC 030 to northwest corner of Section 15	None	533.03'

Description of monument for corner and accessories established to perpetuate locating the position of the c	orner:
---	--------

Set a 3/4" x 24" iron with embedded aluminum cap, stamped "MACOMB COUNTY MONUMENT MI ACT 345", "PCC-030", "34970" set in a OF MICHIGAN monument box in 12 Mile Road.

Set a chiseled "X" in southwest rim of a storm sewer road basin on the north side of 12 Mile Road Az 78º 166.57 Az 96º Set a chiseled "X" in northwest rim of a storm sewer road basin on the south side of 12 Mile Ref 168.50 Set a chiseled "X" in north rim of a gate well and valve on the south side of 12 Mile Road. Set a chiseled "X" in north rim of a Ameritech manhole on the south side of 12 Mile Road. Az 103° 125.15 Az 223° 79.58 Az 292° 94.84 Set a chiseled "X" in south rim of a storm sewer manhole on the north side of 12 Mile Road

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL

SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THIS CORNER.

Signed by <u>349</u>70 Surveyor's Michigan License No.

THE MACOMB COUNTY SURVEY PEER GROUP PREVIOUSLY RATIFIED THIS CORNER'S POSITION

UNDER MICHIGAN PUBLIC ACT 345 OF 1998 AP AY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

MEETING HELD ON 8-7-20;2

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995 Dunn

CRAIG P.

AMEY

SURVEYOR

No.

POFESSION N

LICENSEDA

18

FESSIONAL

MARTIN C. DUNN, P.S. CHAIRMAN



Todd Schmitz Deputy Clerk

Carmella Sabaugh Macomb County

Macomb County
Clerk/Register of Deeds

Betty A. Oleksik Deputy Register of Deeds

REMONUMENTATION PROGRAM
MARTIN C. DUNN. SURVEYOR REPRESENTATIVE
OFFICE: 586-469-7916 ◆ CELLULAR: 810-217-7275

December 14, 2012

Nancy Johnston LARA/Bureau of Construction Codes Office of Land Survey & Remonumentation P.O. Box 30254 Lansing, MI 48909

Dear Ms. Johnston,

Please find enclosed, recorded copies of the following Land Corner Recordation Certificates assigned in the 2012 Grant Year:

T5N/R13E: A03.

T3N/R14E: Other Codes: PCC-045, PCC-046, PC-047, PCC-048, PCC-049, PC-050.

T1N/R13E: Other Codes: PCC-027, PCC-028, PCC-029, PCC-030.

The above referenced Land Corners and Land Corner Recordation Certificates have been entered into the State Corner Index System. Please contact the Remonumentation office at (586) 469-7916 if you have any questions. Thank you.

Sincerely,

Betty A. Oleksik

Macomb County Grant Administrator

Enclosure

BAO/mj

cc: Martin C. Dunn, P.S.

Clerk's Office
40 N. Main St.
Mount Clemens, MI 48043
586-469-5120
Fax: 586-783-8184
http://www.macombcountymi.gov/clerksoffice
clerksoffice@macombcountymi.gov

Fax-on-Demand Michigan: 1-888-99-CLERK Out-of-State: 310-575-5035 Register of Deeds
10 N. Main St.
Mount Clemens, MI 48043
586-469-5175
Fax: 586-469-5130
http://www.macombcountymi.gov/registerdeeds
reaisterdeeds@macombcountymi.gov

RECD MACOMB CO *12DEC13AM0843

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Macomb (County)	_ Located In: City of St. Clair Shores	Corner Code # PCC 030		
1. Public Land Survey	T 1N R 13E T R R			
2. Property Controlling In Section	S T R			
Miscellaneous Property in Sec.	S T R S T R			

2175901 FAGE 1 OF 1 LIBER 21777 PAGE 136 12/13/2012 09:52:07 A.M. NACOMB COUNTY, NI SEAL CARMELLA SABAUGH, REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _ , Recorded Plat

Surveyor's Michigan License No. 34970

5. Private Claims Intersection of the North line of Section 15 with the Northerly line of PC 625

Craig P. Amey , in a field survey on <u>July 12</u>, 2012 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- A -=	C > -	- c		
2 —6—	5	•	3 X	
3 -2-	8	•	19	
t> ————————————————————————————————————	17	16	(15)	$\frac{1}{}$
7 1 8 19	20	21	_	1
9	29-	28 /	N' buy	
11 — 31	32, , ,		* # # T	
13 —				====

Item	Date	L	Р	Document	Name	#	Cor. Desc.
1	1810			Private Claim Description	Greeley		Post
2	1810		****	Private Claim Notes	Greeley		Post
3	1817			Township Plater By THE MACONID C	Preston		Not Indicated
4	1817			GLO NORESUP AS THE OFFICIAL CORN	LER URICESTOMICHIC	AN	Not Indicated


345 OF 1990 AT A MEETING HELD ON 8-7-2012

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

PCC-030 is Intersection of the North line of Section 15 with the Northerly line of PC 625. A research of the public records and a request sent to all area surveyors provided no recorded surveys that reference this corner. To locate the position, I intersected the northerly line of PC 625 as approved by the Macomb County Peer Review group in 2011 and monumented by corners recorded in Liber 21034, Page 781 MCR and Liber 21051, Page 848, MCR, with the north line of section 15 as defined the northwest corner of section 15, as recorded in Liber 6862, Page 831, MCR, and the north quarter corner of Section 15 as recorded in Liber 19067, Page 925 MCR. The corner location is in the center of 12 Mile Road, a bituminous surface, and is located approximately 0.43' south of the centerline of 12 Mile Road.

Distance Comparisons	GLO	AEW
PCC 030 to northwest cor of PC 625 (PC-024)	None	439.67'
PCC 030 to PCC 025	None	2305.83'
PCC 029 to PCC 030	None	465.70°
PCC 030 to north quarter corner of Section 15	None	2165.51'
PCC 030 to northwest corner of Section 15	None	533.03'
		255.05

C.	Description	n of mon	nument for corner and accessories established to perpetuate locating the position of the	orner:
	Set a 3/4":	x 24" iron [.]	n with embedded aluminum cap, stamped "MACOMB COUNTY MONUMENT MI ACT 345", "PC	C-030", "34970" set in a
	monument	box in 12	2 Mile Road.	THE PARTY OF THE P
	Az 78°	166.57'	Set a chiseled "X" in southwest rim of a storm sewer road basin on the north side of 12 Mile I	SOCK OF MICH
	Az 96°	168.50'	Set a chiseled "X" in northwest rim of a storm sewer road basin on the south side of 12 Miles	2 A 2 A 2 A 2 A 2 A 2 A 2 A 2 A 2 A 2 A
	Az 103°	125.15'	Set a chiseled "X" in north rim of a gate well and valve on the south side of 12 Mile Road 🕺	OF CRAIG P. 10 12 1
	Az 223°	79.58'	Set a chiseled "X" in north rim of a Ameritech manhole on the south side of 12 Mile Road *	AMEY 3
	Az 292°	94.84'	Set a chiseled "X" in south rim of a storm sewer manhole on the north side of 12 Mile Road.	PROFESSIONAL :
				SURVEYOR 5
	THE SELE	CTED LO	OCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL 🥞 🤅	No. 34970 8 4 8
	SURVEYO	ORS AS TH	THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THIS CORNER.	
				Photosecon S. S. S.
Sigi	ned by		Date 12-04-12	AND TOPE OF THE PROPERTY OF THE PARTY OF THE
_		/ <u>/</u> /	1 21070	A DECEMBER AND LONG.



ANDERSON, ECKSTEIN AND WESTRICK, INC.


51301 Schoenherr Road, Shelby Township, Michigan 48315 Civil Engineers • Surveyors • Architects 586-726-1234

2012 Remonumentation

Corner: PCC-030 Intersection of the North line of Section 15 with the Northerly line of PC 625

Surveyor's Report

PCC-030 is the Intersection of the North line of Section 15 with the Northerly line of PC 625. In 1817, William Preston, D.S. was contracted to subdivide section 15. PC 625 lies diagonally across Section 15 in a northwest/southeast orientation, extending from the northwesterly corner of Section 15 to Lake St. Clair. Preston does not call out the intersection of the north line of section 15 with the northerly line of PC 625 when he ran the north line of section 15. However, in 2011, we presented our analysis of this location to the Macomb County Remonumentation Peer Review Committee, which definitively proves that the GLO notes are incorrect in their omission of the intersection of PC 625 with the north line of section 15. The 2011 Macomb County Remonumentation Peer Review Committee concurred with our analysis, and subsequently, we have been contracted by Macomb County to locate and, if necessary, remonument this position.




PCC-030 is Intersection of the North line of Section 15 with the Northerly line of PC 625. A research of the public records and a request sent to all area surveyors provided no recorded surveys that reference this corner. To locate the position, I intersected the northerly line of PC 625 as approved by the Macomb County Peer Review group in 2011 and monumented by corners recorded in Liber 21034, Page 781 MCR and Liber 21051, Page 848, MCR, with the north line of section 15 as defined the northwest corner of section 15, as recorded in Liber 6862, Page 831, MCR, and the north quarter corner of Section 15 as recorded in Liber 19067, Page 925 MCR. The corner location is in the center of 12 Mile Road, a bituminous surface, and is located approximately 0.43' south of the centerline of 12 Mile Road.

I believe that the method described above has determined the best location of the Intersection of the North line of Section 15 with the Northerly line of PC 625.

Respectfully Submitted,

Craig P. Amey, PS

Z-B






ANDERSON, ECKSTEIN AND WESTRICK, INC.

Civil Engineers • Surveyors • Architects

51301 Schoenherr Road, Shelby Township, Michigan 48315 Phone 586-728-1234 Fax 586-728-8780

Macomb	Co.
Remoi	1
2012	

DATE	PROJECT NO.
12/12	0223-0036
DRAWN BY	SHEET No.
JJG	
CHECKED BY	PC-625
CPA	
	12/12 DRAWN BY JJG CHECKED BY



No. 87 No. 625 Confirmed to Pierre Duchesne

LAKE ST. CLAIR

Description No. 625 Confirmed to Piere Duchane commencing at a post standing on the border of Lake St. Clair between this tract and unconceded land thence north seventy five degrees west one hundred and mineteen chains sixty four links to a post thence north fifteen degrees east twenty three chains to a post thence south seventy five degrees east one hundred and sixteen chains to a post standing on the border of Lake St. Clair between this tract and a tract of unconceded lands, thence along the border of said lake south six degrees west twenty three chains twenty eight links to the place of beginning, containing two landred and seventy acres and ninety eight immiredths of an acre,

Detroit Jany 4th, 1810

Astron Greeley Surveyor of private claims

N.87. Lake St. Blair Description N. 625 confirmed to Run Dec! are, commencing at a post stands ing on the border of Jake It- Blain between this track and unconceded land, thene with deventy five degrees west one hundre and sinction chains tiply four links to a post thence north fifteen degrees east twenty three chains to a post thence south severity five degrees cust one hundred and sixteen chains, to a post standing on the border of Sake of Clair between this track and a track of unconceded lands, thence along the Border of said take worth six degrees west twenty Three chains twenty eight links, to the place of begin ming containing two hundred and sevs city acres, and viniety eight hundred the of an acre Detroit January 4 1810 Auron Greeley Hurveyor of private Claims.

Township No I North Range No XW East y Mer. (With Hir) 6 W. 610 #5 H 640 43 3 10.00 7. 640 3 N. 640 **. 9** 14. 640 ~13h6.51 10.19 18 1700 et 134418 A 353.84 157.69 ,, 138.68 22 - _...1319.81, 23 19 1. 640 419171 Ó 28 31 32 83 415995 115751 July 1 115959 A 625.34 A low Goppon the Gogard on the costing of the Tango James Missz Partyzo 1444 **(¢**®£ co.7

4-A-3

Form 1. Toute Rounge 13 Bast

East Corrected between 4+9 110.07 made 14 Section corner on a Broken 24 mi dia 80.14 To Section come South Between Sections 9+10 2/0.00 made half mile conver on a B. ash 6 su dia 12.00 a B. ash 18 ms. 80,00 Set frost for Section 9,10,16:15 From Which a B. ach 8 m dia beans S15W 10 links also a B. ask 10 In dia bears N 85 & 11 links dist Inter W. Oak Poplar B. ath Elm Sugar B. ash + Undergrowth Spice Black West On Randon between 59+16 80.00 Set lengty half mile port Land level and dry good 200 pale Loud level Timber WOak B. ach Elm Sugar Poplar & Undergrowth East Consected between 9+16 40,00 Set 14 Section for from which a Sugar 24 moles bean 552 820 lin also a Buch 12 mo di bear 832 m 12 lendes des 80,00 To. Section Comer South Between Sections 16+15 22.85 au Elen 14 m di

Jour I North Ronge 13 Bast 40,00 Made half mile Comer one a W. Oak 6 m de 41.17 a B. Weste 16 m di 80,00 Set post for Section 16.15:22,21 have Which a B. Oak If in di bears S. 5 & 11 lin also a 13. Cich 16 in di bears N'30 W 25 links 12 half mile level and wet 2d pale last half mile same Simber B. asti Beech Elen Lumi + Undergrowth Lynn B. Orale to 1124 Int probate claim Nº 625- Confirmed to Perse Inchersia 50.6-South of the N.N. Con their of Made Cor for frao sects 15416 on an ash 8 in clian East 22,01 Left the claim 5,76 four the S.W. Con thereof made Cor for frac. Dec 15:16 as B. ash 14 m cham This claim was not observed in Rumino the sectional when the fact notes were miade West On Randow between S. 16+21 4000 Set tempy half mile frost 80,20 But West boundary 15 link South of comer Land level Part dry 2 take Timber B. ash Beech Sugar Lym Undergrowth Spice + c East Com between 16+21 4/10 Made'ly section comer on a B. ash 7 in slice at average distance

4-4-4

Jum 1. nte Range 13 East 80.00 Set front for sections 10.11-14.15 from Which a Beech 14 in di bear N 23 & Tlinks also a Buch bin dia bears NOS W 6 links cliet fuithalf mile good 2th nate Finited W.Oak Buch Sugar v-Mudergrowth spice West Ou Recedan between 5.10 +13 4000 Set leaf half mile for 80,04 Buld West boundy atthe Comer Land level Part dry 2 - sale Timber Buch Elin to East Corrected between 10+15 40.02 Made 14 Section Comer on a Beach 4 m di at average dietand 80,04 To Section Consum East Between Sections 11+14 38.37 Inter Lake St Clair and Set frost for fracul sections 11414 from which of Sycamore 18 m di bears N 37 8 53 links also a Maple 12 m bears 847 W 45 Timber Beech B. ash Elm to South Between Sections 14+15 5.00 a B. ash 18.m dia 29.68 Interes of Prot claim 80.56 from N.W. comer of Lot No 6.25 and Made Comer on our homood 4 ins

dia for had sect 14+15=52.60 left


Jun 1. oute Range 13 East 10,00 Set post for sections 10.11-14.15 how Which a Beach 14 in di bear N 23 & Plinks also a Back bin die bears NOS W 6 links dielfuthalf mile good 2th nate last tell mile same Finited W.Oak Buch Sugar x-Undergrowth sprice West Ou Roundary between 5.10+15 4000 Set temp half mile for 80,04 End West boundy atthe Comer Land level Part day 2 to pale Fruit Buch Elin 40 East Corrected between 10+15 40.02 Made 14 Section Comes on a Buch 4 m di at average dietance 80,04 To Section Corner East Between Sections 11+14 38.37 Inter Lake St Clair and Det frost for fracul sections 11414 from Which & Sycamore 18 m di bears N 37 & 33 links also a Maple 12m bears S47 W45 littles diet Tom past Any 2t rate Timber Beech B. ash Elm to South Between Sections 14+15 5:00 a B. ash 18 m dia 29.68 Interes & Brot Claim 80.56 from

N.W. comer of Lot Nº 6.25 and

Made Comer on our Brownood 4 ms

dia for pad sect 14+15=52.60 left

4-A-4



PLAT MACK AVENUE FARMS Nº1 SUBDIVISION"

S.W 4 of S.W. 4 of Sec 10 and Partoff 625 TINR 13 Erin- Twp Mecomb County Michigan.
Scale 200 ft. = linch.

Walter J. Donner County Engineer MtClemens, Mich.

april 30-1920

Mesenger

	68 68	67		46	45		24	25
)	69	66	*	. 47	. 44	AVE	25	22
ŀ	.70	65		: 48	43		. 26	21
,	71 !	64)	. 49	42		27.	20
Ŀ	72	63		, 50	41		28	19
Ŀ	73	62		- 51	10		29	18
,	74	61		52	39		30	17
	75	60		53	38		. 31	192.70
Ŀ	76	. 59		. 54	37		المجترى ا	15
[77 ·	58	4.7	. 55	- 36	7	· 33	/9-63 /4 A
65/	78	57	Š	£ 56	\$ 35 g	W.	94	1972
286	7 / Z		JEW 8	5 6	7 8	A>	1856/	11 125

RECONSTITUTES CHEMICH COUNTY OF MACONIE. AD-1084

LUNGTY TEXASTITIES CHATCHEATA

This was Carrier, That Give a less Tax Liens or This was by the Carrier, That Give a less to Tax Liens or This was by the Carrier of any individual appearing and that all Thires on Larva discalled in the expected increment have been paid FIVE YEARS print to the date thereof, according by the records of this print, and the control of the print of the control of the control

I HEREB CERTIFY THAT THE PLAT HEREON DELINEATED IS A CORRECTION AND THAT PERMANENT MONUMENTS, CONSISTING OF 🖖 🝜 GALVANIZED PIPE 18:

LONG, HAVE BEEN PLANTED AT POINTS MARKED THUS (0) AS THERON SHOWN AT

OF STREETS OR STREETS AND ALLEYS.

AT A MEETING HELP ALZZ (EZ)

ALL ANGLES IN THE BOUNDARIES OF THE LAND PLATTED, AND AT ALL INTERSECT

CERTIFICATE OF MUNICIPAL APPROVAL.

THIS PLAT WAS APPROVED BY THE TOWNSHIP GOARD OF THE TOWNSHIP OF THE

holan &

Place of boginning 3E lok of Sec. 2. Erin Twy T.I. N. 113 E.

and Michigan Taxestment Company, by Richard G. Lombrecht, President and Carl Wisner Secretory" as proprietors, MAYE CAUSED THE LAND EMBRACED IN THE ANNEXED PLAT TO BE SURVEYED, LAID OUT

AND PLATTED, TO BE KNOWN AS MACK AVENUE FARMS NO. 1." SUBDIVISION, 8.420F S.W.3 OF SEC.10. AND PART OF 625 T.I.N.R.13E. LAKE TOWNSHIP, MACOMB COUNTY, MICHICAN. AND THAT THE STREETS AND ALLEYS AS SHOWN ON SAID PLAT ARE HEREBY PROICATED TO THE USE OF THE PUBLIC.

SIGNED AND SEALED IN PRESENCE OF Charl Ruck STATE OF WICHIGAN.) SS.

MY COMMISSION EXPIRES - 1511930

THE ABOVE DEDICATION, AND ACKNOWLEDGED THE SAME TO BE THEIR FREE ACT AND DEED. also

TO ME PERSONALLY KNOWN, WHO BEING EACH BY ME DULY SHORN DID SAY THAT THEY ARE THE PRESIDENT AND SECRETARY RESPECTIVELY OF THE Michigan American Con Licensey CORPORATION, AND THAT THE SEAL AFFIXED TO SAID INSTRUMENT IS THE CORPORATE SEAL OF SAID CORPORATION AND THAT SAID INSTRUMENT WAS SIGNED AND SEALED IN BEHALF OF SAID CORPORATION BY AUTHORITY OF ITS BOARD OF DIRECTORS AND THE SAID AND A Santon Beautiful of Carl Ha CORPORATION BY AUTHORITY OF ITS BOARD OF DIRECTORS AND DEED OF BAID CORPORATION. Resolution, Liber 3168 9. 148

ON THIS DAY OF MARKET TO BEFORE ME A NOTARY PUBLIC IN AND FOR SAID COUNTY, PERSONALLY CAME THE ABOVE NAMED AND TO BE THE PERSONS WHO EXECUTED

criation of Land Platted FARMS Not Tubdice sion SW. Hart SW. Last Sec. 12 and Each of F.C. & R.S. T. M. P.C. S. L. Lin. Two. Maco nick Lower St. Michigan

St. dos dos dolors Beginning at the SECH of SEC 9


Lin Top. Hance northwaker to sech; thence northware
18877 11; thence 305 37 30 N. 1341.83 Ft.; thence 30 34 30 C
1882 51. It the place of beginning.

Junil CLERK.

Muman Tike

4-A-6

389 (Part of Let 27) SHEET 1 OF 2 % SEC.16, FRL SEC.15 & R.C. 625 TANKISE. CLAIR SHOKES MACOMB CO. MICH. VILLAGE OF ST 35ALE 1" × 200" Walter 1 Lehner Reg. C. Mr. Clemens Mich. PHILE 19 10 17 16 1.5 12 MACK AZZESON OF THE VILLAGE OF ST. CLAIR on this day of and on the new on the control of the person who act and deed as such issues 18:19 b- 28. 1432 DESCRIPTION The land embraced in the ennexed plat of "abbabble Plats No. 24% of parts of N.E. Frit bec. Fri. 800. 10, and P.C. 628, T.I. N.R. 13 S. Village of St. Claim Shores, Recemb Co., Mich.; and Fribod as Collows: Beginning at the N.R. corner of thence S. 1948730" V. 304.30 ft., th S. 2010'20" V. 141.60 ft., thomas N. 1027.43 ft., thence N. 1948'30" N. 2 thence N. 87°25'30" V. 1807.13 ft. -62'30" E. 1346.30 ft., thence S. 37° E. and Wd lins of Sec. 15, 173.22 f N. 2008'30" E. 208.62 ft., thence C. incing.



SURVEY & REMONUMENTATION

APR 2 9 1996


COMMISSION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	•				
Macomb (County)	Located In: C Erin\Lake Tov	Corner Code #G5 vnship			
1. Public Land Survey	T 1N R 13E G5 T R — — T R —				
Property Controlling in Section Miscellaneous Property in Sec.	TR		Re	gister of Deeds S	tamp & File Number
4. Lot No, Reco	rded Plat		A B C	D E F G 1	H I J K L M
Michigan P.A. of 1970, the or regulations and rules therefore Department of the Interior, Bu corner points mentioned in lines Land Surveyors or by a Decree recovered, found as expressed to	urvey on August 8, 1995 do hereby certify that other points mentioned in lines 1 and 2 at as required in the current manual of survey I reau of Land Management or by a decree of 3, 4 and 5 above were in conformance with the of a Court of Law; established, re-established relow:	owe were in conforman instructions of the United a Court of Law and for he rules of the Michigan E I, monumented, re-monu	ce with the states in that the sound of mented, 7	20 21	10 11 12 13 13 13 13 13 13 13 13 13 13 13 13 13
on this certificate.			10 30 11 12 31 12	32 33	34 35 35
A. Description of original m	onument and accessories and/or subse	equent restoration:			
1818 GLO	Willam Preston	No witnes	ses remain		
No evidence of the corns monumentation in subdis corner, and it has interior Congress and Washington also fit the centerline of the Congress record distant section 9. Record distant	er was found. Due to the widening or issions adjacent to the corner. "Mac roads from which the corner could on fit the centerline of the roads. Iro he roads. The south line of section e to the section line. The centerline ce along the south line of section 9 Washington (1332.50R 1332.38R)	of 12 Mile Road and k Avenue Farms No be reestablished. It ins found at the inter 9 was established to of Washington was fit the existing center	Little Mack Road, b. 2" is located in to rens found at the insection of Harding by extending the consecution of the consecution	intersections of I g, Coolidge, Co enterlines of Hai east establishing	Harding, Coolidge, ngress and 12 Mile rding, Coolidge and the east line of
c 2688 21 Factor	uarter post of section 9 (G4) (GLO: uarter post of section 16 (G6) (GLO trior comer and accessories established	> = 40 ch}	g the position of the	corner:	
150° 72.48 228° 68.32 314° 75.72	IRON WITH MCR CAP #34970 IN A Set PK and Tag #17365 in the sou Set PK and Tag #17365 in the not Set PK and Tag #17365 in the sou Set PK and Tag #17365 in the not cepted by me and is generally accepted	ithwest face of a util thwest face of a util ithwest face of a util thwest face of a util	lity pole ity pole lity pole ity pole	Table evidence of t	the position of the
-	ACCEPTED BY THE MACON GROUP AS THE OFFICIAL OF PUBLIC ACT 345 OF 19: ON 8-15-95 WILLIAM E. SODERB	THENCH CHAPEL WAS A.		PROFE SUR	MICHIGAN AIG P. MEY SSIONAL VEYOR NO.
Signed by	fly	Date	12.15.95	PROFE	SSIONAL
Surveyor's Michigan Vic	ense No. 34970	FORM	n approved by Michigai	STATE BOARD OF LAN	ND SURVEYORS, JAN. 28, 197 REVISED MAY 14,1976 REVISED JAN. 198

RECT NOV 2 0 2007 12 15 pm

found as expressed below:

H-5




LAND CORNER RECORDATION CERTIFICATETION Filing Requirement of Act 74, Mich. P.A. 1970

For	comers	ln
-----	--------	----

Macomb (County)	Located In: City of St. Clair S	Corner Code # hores	7158676
1. Public Land Survey	T <u>1N</u> R <u>13E</u> T R T R	<u>H-5</u>	LIBER 19067 PAGE 925 11/29/2007 09:11:22 A.N. HACOND COUNTY, NI SEAL CARNELLA SABAUGH, REGISTER OF DEEDS
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR		Register of Deeds Stamp & File Numb
4. Lot No, Ro	ecorded Plat		2 - 5 - 4 - 3 - 2 - 3 - 2

I, Robert H. Birkett, In a field survey on, August 24, 2007 to hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



Description of original monument and accessories and/or subsequent restoration: A. Description of original monument and accessories and/or subsequent restoration:

Common corner between section 10 & 15. Wood post was set by the General Land Office in 1818.

a. 1912 G Jerome #2, "Bay View Sub.", L. 2, P. 104

b. 1919 WJ Miller #67, "Lake Shore Little Farms Annex No. 1", L. 3, P. 181

d. 1919 JW Irwin (CE), "Elm Grove Gardens", L. 3, P. 168

d. 1919 WJ Miller #67, "Lake Shore Little Farms", L. 3, P. 159

Unknown (CE), "Mack Avenue Farms No. 1 Sub.", L. 4, P. 55

f. 1922 WJ Miller #67, "Visnaw's Lake Shore Gardens", L. 6, P. 4

g. 1923 Jinknown "Visnaw's Lake Shore Gardens Anney" I 6 P. 48

g. h, 1923

1. 1925

1925 j. k. j.

1925

1930

1930 m.

1938 n.

WJ Miller #67, "La Chance and Richard's Little Farms Sub." L. 6, P. 3
Unknown, "Visnaw's Lake Shore Gardens Annex", L. 6, P. 48
WJ Lehner #123, "John V. Sheehan's Sub.", L. 10, P. 11
G Jerome #2, "Daiby and Campbell's Harper Ave. Sub. No. 1", L. 9, P. 6
G Jerome #2, "Daiby and Campbell's Harper Ave. Sub.", L. 9, P. 5
WJ Lehner #123, "Assessor's Plat No. 26", L. 15, P. 11
WJ Lehner #123, "Assessor's Plat No. 24", L. 15, P. 6-7
V Wilson #3032, "Assessor's Plat No. 47", L. 19, P. 34
V Wilson #3032, "Assessor's Plat 56 of Greendale Acres Sub.", L.21, P. 40
WJ Lehner #123, "Trombley-Wentworth Sub.", L. 24, P. 18
C. Postiff #6894, "Rossin & Ringler's Champine Acres", L. 29, P. 3
TH Postiff #6522, "Rossin & Ringler's Champine Acres No. 2", L. 30, P. 1
V Wilson #3032, "Richmond Gardens Sub.", L. 36, P. 32 1942 0.

1947

1953 q.

1954



8. Description of comer evidence found and/or method applied in restoring or reestablishing corner: Obliterated corner has been restored using found irons along 12 Mile east and west of Harper, c, h & p from section "A" above. The location is at the centerline of asphalt 12 Mile Road and the centerline of asphalt Harper.

Field Measurements Between Comers (See reverse side)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set a 3/4" x 24" Iron with an aluminum cap stamped "Macomb County Monument, Mi ACT 345, 41094, H-5" at the intersection of 12 Mile Road and asphalt Harper, in a new monument box.

60° - 78.20′ - Center top nut hydrant north side 12 Mile. 134° - 78.04′ - Chiseled "x" north rim of MBT man hole.

225° - 85.30' - northeast comer concrete planter curb.

230° - 169.78' - Northeast corner brick building #29519.

AZ AZ AZ AZ 310° - 79.78' - Center top hydrant north side 12 Mile Road.

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original comer.


ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 9-18-07

MARTIN C. DUNN, P.S. CHAIRMAN

10-31-0

Surveyor's Michigan License No.

Form Approved By Michigan State Board Of Land Surveyors, Jan. 25, 1971 Ravised May 14, 1975, Ravised Jan., 1983, Ravised Oct. 1985



LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

F	or	COL	ners	in
---	----	-----	------	----

Macomb (County)	Located In: City of St. Clair Shores	Comer Code # PC 024
1. Public Land Survey	T <u>1N</u> R <u>13E</u> T R	
2. Property Controlling in Section	S T R	
3. Miscellaneous Property in Sec.	\$	

1237201 LIBER 21034 PAGE 781 12/15/2011 09:05:49 A.M. MACOMB COUNTY, HI CARMELLA SABAUGH, REGISTER OF DEEDS

Register of Deeds Stamp & File

4. Lot No. Recorded Plat

5. Private Claims Northwest Corner of PC 625

Craig P. Amey , In a fleld survey on July 30, 2011 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed ballows.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

A B C D E F G H .	
2 0 0 0 0	7
3	
4-2-0-0-0-0	
5	
5 19 19 19	
7	
8 - 19 - 10 - 10 - 10 - 10 - 10 - 10 - 10	
9	
10	
12 3 3	
13	

						137	
item	Date	Ļ	P	Document	Name	#	Cor. Desc.
1	1810	-		Private Claim Description	Greeley		Post
2	1810	-	_	Private Claim Notes	Greeley		Post
3	1817	-	_	Township Plat	Preston	******	Not Indicated
4	1920	4	55	Mack Avenue Farms No. 1 Sub.	Lehner	123	Not Indicated
5	1924	7	50	Roseville Gardens Subdivision	Lehner	123	Not Indicated
6	1930	15	6	Assessors Plat No. 24	Lehner	123	Not Indicated
7	1955	32	49	Assessors Plat No. 60	Bridges	5779	Not Indicated
8	2011			MCPEDD Tax Map	4-1		

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A research of the public records and a request sent to all area surveyors provided no recorded surveys that reference this corner. The only plat that dimensions this location is Mack Avenue Farms No 1 Subdivision, as recorded in Liber 4 of Plats, Page 55, Macomb County Records (Figure 1). The plat clearly shows the corner to be north of north line of Section 15 (centerline of Champaigne, as shown is the north line of Section 15). According to the GLO Township Plat this comer should be south of the northerly section 15. The GLO notes also do not show the Private Claim line intersecting the northerly line. After reviewing the notes, the township plat, and having discussions with other surveyors, I believe that the section was improperly surveyed by inadvertently omitting calls to the intersection of the west line and north line of section 15 with PC 625. (Cont on back)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set a 4" x 36" concrete monument with embedded aluminum cap, stamped "MACOMB COUNTY MONUMENT MI ACT 345", "PC—024 REF. PT.", "34970" set in grass of parkway between the sidewalk and the back of curb of westbound 12 Mile Road, 100.00 feet southwesterly from the northwesterly comer of PC 625 (PC-024).

Az 23º 91.81 Sw comer of Mobile gas station. Az 136° 96.71" Center of top of hydrant on the south side of 12 Mile Road, East of Little Mack Set CST nail w/tag #34970 In north face of utility pole w/camera at northeast Az 267º 44.32 corner of 12 Mile Road and Little Mack Avenue. Az 312° 23.33' Set a chiseled "X" in southeast corner of concrete base for Mobile" sign

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THIS CORNER.

Signed by ACCEPTED BY THE MACOMB COUNTY SURVEY PEER Surveyor's Michigan License No.

Date DEC 09, 2011

GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING APPROPED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, ON /1-2-201/ Injustic C Fluori MARTIN C. DUNN, P.S. CHAIRMAN

Revised May 14, 1975

OF MICHIGA

CRAIG P. ALIFY

ROFESSIONAL BURVEYOR No. 34970

POFESSIONA

4-13-3

Liber 21034 Pase 782

Macomb (County)	- 2	Located In: of St. Clair Sh	ores		Comer Code # PC 024
1. Public Land Survey		T 1N T	R	13E	
2. Property Controlling In Section	s	_ +	R R R		
3. Miscellaneous Property in Sec.	. s . s	_ <u> </u>	R		

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(Cont. from front) In 1818, William Preston, Deputy Surveyor, surveyed Town 1 North, Range 13 East. Section 15 is a fractional section, and therefore did not follow the normal sequence of subdividing a section as set forth in the 1815 instructions, issued by Edward Tiffen, Surveyor General. As a result, the west line of Section 15 was the first line surveyed and it was surveyed from North to South, as shown on page 234 of the GLO notes. On Page 239, Preston surveyed the north line of Section 15 by running a random line and correcting back. Any reference to a Private Claim was also omitted from this line. Also on Page 239, Preston surveys the east line of Section 15. As he is running this line, he notes the Private Claims. I believe that at this point, Preston realized his error and attempted to correct his error. It is clear, based on calculations using Preston's dimensions, that this comer does fall northerly of the north line of section 15, as shown on Mack Avenue Farms No.1 Subdivision.

Therefore, I used the dimensions from Mack Avenue Farms No.1 Subdivision to set the location of this corner relative to the section lines of Section 15.

The corner position cannot be monumented because it falls within a structure (currently a gas station). An alternate location along the northerly or westerly line of PC 625 at the right of way of 12 Mile Road also was not suitable due to asphalt paving. We opted to set the monument along the westerly right of way line of PC 625 in the grassy parkway between the sidewalk and curb of westbound 12 Mile Road.

Distance Comparisons	GLO	AEW	DIE
Nwly cor of PC 625 (PC-024) to Swly cor of PC 625 (PC-023)	23.00ch (1518.00°)	1514.10	3.90
Nwly cor of PC 625 (PC-024) to int of E line of Sec 15 with Nly line of PC 625 (PCC-025)	80.56ch (5316.96')	5588.94	167.87

RECEINACONE CO *11DEC290MOBIG

CORRECTIVE LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Macomb

LCRC is being recorded to correct "PC-025" to "PCC-025" in Section C. LCRC previously recorded on 12/15/2011 in Liber 21034, Pages 783-784.

	(County)	•	City of St. Clair Shores	PCC- 025	
1.	Public Land Survey		T 1N R 13E		
			T R		
2,	Property Controlling In Section	S	T		
3.	Miscellaneous Property in Sec.	S S	Ť Ř		

1241339 LIBER 21051 PAGE 848 12/29/2011 08:29:44 A.M. MACORB COUNTY, NI SEAL CARRELLA SARAUGH, REGISTER OF DEEDS

Register of Deeds Stamp & File

G

R

2

s 6

8

, Recorded Plat 4. Lot No.

5. Private Claims Intersection of the Line Between Fractional Section 14 and 15 with the Northerly Line of Private Claim 625

I, <u>Craig P. Amey</u>, in a field survey on <u>July 30</u>, 2011 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were an experimental with the uniter of the Michigan Board of Land Survey and the survey and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. D	escriptio	n of or	iginai mo	12 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3				
lte	m	Date	L	Р	Document	Name	#	Cor. Desc.
1		1810	_		Private Claim Description	Greeley	-	Post
2	!	1810	_		Private Claim Notes	Greeley		Post
3	i	1817	_	-	Township Plat	Preston		Not indicated
4		1925	9	90	Mylls Subdivision	Lehner	123	Not Indicated
5		1965	175	20	Mylis Subdivision No. 1	Brown	2967	Not Indicated

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MCPEDD Tax Map

PCC-025 is the intersection of the line between Fractional Section 14 and 15 with the northerly line of Private Claim 625 (PC 625).

In Aaron Greeley's description of Private Claim 625, dated January 4th, 1810, there is no reference to a section line. Since the township would not be subdivided until 1818, Greeley's description could not contain a reference to the section line.

A research of the public records and a request sent to all area surveyors provided no recorded surveys that reference this corner. We did find two plats that contained this point. The 1925 plat of Myll's Subdivision, L9, P90, shows the Intersection of the section line and the northerly line of PC 625. The 1965 plat of Mylls Subdivision No. 1 (Figure 1) also shows the section line and the northerly line of PC 625. In both plats, no dimensions or ties of any type are included to define the location of the Intersection of the northerly line of PC 625 and the section line. It is my opinion that the northerly line of PC 625 is indicated on the plat in an approximate location for informational purposes only. There is no evidence that the northerly line of PC 625 was surveyed in the preparation of the plats. (Continued on back)

The corner falls in the garage of house #22406 Mylls St. A reference point is set at the right of way of Mylls Street

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 4" x 36" concrete monument with embedded aluminum cap, stamped "MACOMB COUNTY MONUMENT MI ACT 345", "PCC—025

REF. PT.", "34970" at the intersection of the southerly right of way line of Mylls Avenue and the easterly line of Section 15, 37.6 feet north of PG 025. PCC 025

Az 70° 64.55 Set CST nail w/tag #34970 in northwest face of a utility pole w/tight. Az 158º 35.26 Ne comer of brick garage #22406 Mylls. Az 255° 37.81' Ne corner of brick garage #22328 Mylls. Az 340º 54.54 Set a chiseled "X" in north rim of GVW

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THIS CORNER.

Signed by Surveyor's Michigan License No **3**4970

LICENSED **SURVEYOR** No. 34970 PROFESSIONA Date <u>Dr. 28, 2011</u>

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS,

E OF MICHIQ

CRAIG P AMEY

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For comers in

Macomb (County)	Located In: City of St. Clair Shores	Corner Code # PCC- 025				
1. Public Land Survey	T <u>1N</u> R T R	13E	Liber	21051	Pase 849	>
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R S T R					

, Recorded Plat

Section B continued

To set the position for this comer, we first established the southerly line of PC 625. The township plat and Aaron Greeiey's description both indicate that the north line of PC 625 is intended to be parallel to the south line of PC 625. Using the Northwest corner of PC 625 as determined from the plat of Mack Farms Subdivision No 1, I extended a line from that comer on a bearing parallel to the south line of PC 625 to the intersection of the section line between fractional sections 14 and 15 to establish the position of the corner.

The township plat, prepared by William Preston in 1818, Indicates a distance of 29.68 chains from the northeast comer of section 15 to the intersection of the northerly line of PC 625. I believe this distance to be erroneous. After examining Preston's dimensions for the entire section line, I believe that Preston has approximately a 9 chain error located in this northerly portion of the section line (see attached "Analysis of Original Survey Errors"). Therefore I did not use Preston's distance.

A rough comparison of the position I have determined against the position indicated by Preston's dimensions can be made by examining the positions relative to Mylls Subdivision No 1. Although Myll's Subdivision has no dimensions to the PC line, an approximate dimension can be scaled. I scaled a distance of 60 feet from the southeast comer of the sub to the PC line. My calculated distance falls 70 feet from the southeast comer of the sub, a difference of approximately 10 feet. Using Preston's dimension, the Intersection falls approximately 250 south of the intersection as graphically shown on the plat, or 190 feet south of the subdivision. Although I cannot use the plat to confirm the exact position that I have determined, I think it is clear from the plat comparisons that Preston's dimension is grossly erroneous and cannot be used to determine or confirm the intersection position.

Distance Comparisons	GLO	AEW	Diff
Nly line of PC 625 (PCC-025) to sly line of PC 625 along section line (PCC-026)	22.92ch (1512.72')	1607.51	65.17'
Nwly cor of PC 625 (PC-024) to int of E line of Sec 15 with Nly line of PC 625 (PCC-025)	80.56ch (5316.96')	5588.941	167.87

ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD
ON 1/- 2 - 20/1

MARTIN C. DUNN, P.S. CHAIRMAN

^{5.} Private Claims Intersection of the Line Between Fractional Section 14 and 15 with the Northerly Line of Private Claim 625