

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
 ERIN TOWNSHIP

For corners in

<u>MACOMB</u> <small>(County)</small>	Located In:	Corner Code #
1. Public Land Survey	T <u>1N.</u> R <u>13E</u>	<u>H-03</u>
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling	S _____ T _____ R _____	_____
in Section	S _____ T _____ R _____	_____
3. Miscellaneous	S _____ T _____ R _____	_____
Property in Sec.	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

205068
 LIBER 9942 PAGE 533
 12/26/2000 09:19:20 A.M.
 MACOMB COUNTY, MI
 CARMELLA SABAUGH, REG/DEEDS

Register of Deeds Stamp & File Number

I, JOHN R. FENN in a field survey on September 16, 2000 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Glo 1817 Wampler No evidence of original corner

No Recorded LCRC's
 Plats;

- | | | |
|------|------------------------|----------|
| 1932 | Assessor's Plat No. 35 | L15, P24 |
| 1956 | Couchez Farms | L35, P38 |
| 1956 | Couchez Farms No. 2 | L37, P26 |
| 1959 | Couchez Farms No. 3 | L46, P9 |

ACCEPTED BY THE MACOMB COUNTY SURVEY PEER BOARD AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD
11/21/00

 WILLIAM C. ... CHAIRMAN

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

There was nothing marking the corner. This corner is West of the Intersection of 13 Mile Road (concrete) and Harper Avenue. The corner position was determined by irons located in "Couchez Farms" to the South and verified by irons to the East and West.
 Distances: H-03 to I-03 H-03 to G-03
 GLO 40 chains or 2640 feet GLO 40 chains or 2640 feet
 Measure 2716.04 feet Measure 2703.27 feet

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I recommend that a standard 3/4" Iron Rod with a standard Macomb County Remonumentation Cap marked Act 345 23505 in a new monument box be located at the determined position.

- | | | |
|-------|---------|---|
| N70°W | 94.65' | Set PK nail with Macomb County Remon tag in South face Utility Pole |
| S35°E | 138.06' | Northwest corner of Wendy's building |
| S80°W | 224.76' | Northeast corner of Kroger building |
| N05°W | 73.80' | Northwest corner of house #21455 |
| South | 43.00' | Found Iron on South Right of way |

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best position of the original corner.

Signed by John R. Fenn
 Surveyor's Michigan License No. 23505



Date 12-19-2000

H-03

ERIN TOWNSHIP

T.1N.,R.13E.

SOUTH QUARTER CORNER SECTION 3

NORTH QUARTER CORNER SECTION 10

H-03 ERIN TOWNSHIP

RECORDED INFORMATION:

GLO: 1817 Wampler No evidence of original corner

LCRC'S

None previously recorded

PLATS

1932	Assessor's Plat No. 35	L15, P24
1956	Couchez Farms	L35, P28
1956	Couchez Farms No. 2	L37, P26
1959	Couchez Farms No. 3	L46, P9

FIELD EVIDENCE:

This corner is located West of the intersection of 13 Mile Road (concrete) and Harper Avenue. There was nothing at this corner location. We found irons in all four directions. We used the Irons in "Couchez Farms" to the Southwest to establish the corner location. We then used irons in other Subdivision to verify the location.

RECOMMENDATION:

After evaluating the found irons I recommend setting the corner from the above mentioned Irons. This corner would require a new monument box.

DISTANCES:

H-03 TO I-03

GLO 40 chains or 2640 feet

Measure 2716.04 feet

H-03 to G-03

GLO 40 chains or 2640'

Measure 2703.27 Feet

WITNESSES:

N70°E	94.65'	Set PK nail/remon tag in South face utility pole
S35°E	138.06'	Northwest corner of Wendy's building
S80°W	224.76'	Northeast corner of Kroger building
N05°W	73.80'	NW corner House #21455
South	43.00'	Found Iron on South ROW