

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MACOMB
(County)

Located In: Chesterfield Township
Corner Code ## A-9

RECORDED IN MACOMB COUNTY
RECORDS AT 8:30 A.M.

DEC 28 1993

Register of Deeds Stamp & File Number

- 1. Public Land Survey T 3N R 14E A-9
2. Property Controlling in Section S T R
3. Miscellaneous S T R
4. Lot No. Recorded Plat
5. Private Claims

Grid table with columns A-M and rows 2-13. Contains numbers 1-36 in a grid pattern.

I, Shelby W. Money, in a field survey on November 18, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- GLO POST, NO WITNESSES REMAIN
LCRC (1977) L 2862 P. 854 STONEROCK #13601 CORNER CODE #A-9
LCRC (1990) L 4990 P. 164 STEVEN DUNN #25408 CORNER CODE #A-9
LCRC (1991) L 5024 P. 934 DeDECKER #8386 CORNER CODE #A-9

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND RAILROAD SPIKE
THIS CORNER VERIFIED BY:
FOUND ALL RECORDED WITNESSES
HUEGEL FARM ACRES SUBDIVISION MACOMB TOWNSHIP UNRECORDED
FOUND 1/2" REBAR BELOW RAILROAD SPIKE

ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 12-15-93
FRANK J. DeDECKER, PS, PE, CHAIRMAN

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- REMOVED RAILROAD SPIKE AND PK NAIL AND REPLACED WITH 3/4" BAR WITH MACOMB COUNTY REMONUMENTATION MARKER #30092 IN A MONUMENT BOX
WITNESSES:
Az 06- 44.53' FOUND A PK IN THE WEST FACE OF A UTILITY POLE
Az 57- 73.35' FOUND A PK WITH "SDA" TAG IN THE NORTHWEST FACE OF A 24" TREE
Az 109- 96.10' FOUND A PK IN THE SOUTHWEST FACE OF A UTILITY POLE
Az 227- 106.10' FOUND THE NORTHWEST CORNER OF HOUSE #24980



The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by Shelby W. Money Date 12/14/93
Surveyor's Michigan License No. 30092

# MACOMB COUNTY REMONUMENTATION

CORNER # A-9 T 3 N - R 14 E CHESTERFIELD TOWNSHIP  
COMMON DESCRIPTION S.W. CORNER SECTION 19

## RECORDS RESEARCH

(refer to date, Liber & Page, source, map #, etc.)

### ACT 74 RECORDED FORMS -

L.2862	P.854	Stonerock	(1977)	set railroad spike
L.4990	P.164	Steve Dunn	(1990)	found railroad spike
L.5024	P.934	DeDecker	(1991)	found railroad spike

### ACT 132 RECORDED FORMS -

### GLO NOTES -

Plat

### DEEDS -

None

### UNRECORDED INFORMATION -

None

### ROAD COMMISSION INFORMATION -

### TAX MAPS -

Aerials 9-19E

# MACOMB COUNTY REMONUMENTATION

CORNER # A-9 T 3 N - R 14 E CHESTERFIELD TOWNSHIP  
COMMON DESCRIPTION S.W. CORNER SECTION 19

## FIELD RESEARCH

{AEW Field Book #1193 / Page 8}

**SITE CONDITIONS** (TYPE OF ROADWAY, FIELD, SWAMP, ETC.) -  
Asphalt road ends  
10' west

### RECORDED EVIDENCE OF CORNER -

L.C.R.C.	L.2862	P.854	Stonerock	(1977)
L.C.R.C.	L.4990	P.164	Steve Dunn	(1990)
L.C.R.C.	L.5024	P.934	DeDecke	(1991)

**FOUND EVIDENCE OF CORNER AND CONDITION -**  
Found railroad spike

**FOUND RECORDED WITNESSES -**  
Found all witnesses

**FOUND EXISTING OCCUPATION -**  
Ditch south  
Tree line north  
Road east/west

**SET NEW WITNESSES -**  
No

**MEASURED REFERENCES -**  
None

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

CHESTERFIELD TWP., MACOMB CO.  
 FOR CORNERS OF - LOCATED IN - CORNER CODE NUMBER

1. PUBLIC LAND SURVEY ..... : 3 X B. 14 X. A-9; B-9.

2. PROPERTY CONTROLLING IN SECTION ..... : N. W. 1/4

3. MISCELLANEOUS PROPERTY IN SECTION ..... : N. E. 1/4

4. LOT NO. RECORDED PLAT

5. PRIVATE CLAIMS

A454053

RECORDED IN MACOMB COUNTY RECORDS AT 11:45 A.M. OCT - 7 1977

*[Signature]*  
 CLERK - REGISTER OF DEEDS  
 MACOMB COUNTY, MICHIGAN

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Gary R. Stonerock do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September 26, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on September 26, 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

- A-9; set railroad spike with cut 'X'
- B-9; set railroad spike with cut 'X'

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

- SET RAILROAD SPIKES
- A-9; Re-established N.W. Section corner of Section 30 using the ties indicated on the "RANCH ACRES" subdivision (see attached drawing: # 1951-D, 2 sheets).
  - B-9; Re-established the N. 1/4 corner of Section 30 using the ties indicated on the "SUPERVISOR'S PLAT No. 19", "REPLAT OF LOTS 3 thru 6" (see attached drawing: # 1951-D, 2 sheets).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- SET RAILROAD SPIKES
- A-9; N 0°05' W, 44.53'; P.K. nail in W. side of power pole
  - S 55°14'50" E, 68.38'; nail & tin in N. side of 12" apple tree
  - S 26°53' W, 26.86'; nearest face of corner metal fence post
  - B-9; N 77°46'20" W, 71.60'; P.K. nail in S. side of power pole
  - S 34°12'40" E, 75.38'; N.E. corner of conc. block foundation
  - S 1°14'20" E, 28.59'; nail & tin in W. side of 14" maple tree
  - S 47°32' W, 98.79'; N.W. corner of conc. block foundation

SIGNED BY *[Signature]* DATE October 5, 1977

SURVEYORS MICHIGAN REGISTRATION NO 13601

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO 13601



FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971 REVISED MAY 14, 1978

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

*[Handwritten mark]*

00646

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Macomb  
County

Located in Chesterfield Corner Code   

RECORDED IN MACOMB COUNTY  
RECORDS AT: 11:35 A.M.

NOV - 8 1990

*Ed*

CLERK - REGISTER OF DEEDS  
MACOMB COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

1	Public Land Survey	T	3N	R	14E	B-8
		T	3N	R	14E	B-9
		T	3N	R	14E	A-9
		T		R		
2	Property Controlling	S		T	R	
	in Section	S		T	R	
3	Miscellaneous	S		T	R	
	Property in Sec.	S		T	R	

4 Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5 Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	J	K	L	N
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	18	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Steven E. Dunn, in a field survey on April 15, 16 & 30 19 90  
do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- B-8 Set 1/2" 1. Rod Cap # 30081  
Established N. - S 1/4 Line & E - W 1/4 Line and Set  
At the Intersection of Same
- B-9 Fd. P.K. Nail
- A-9 Fd. Railroad Spike

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

- B-8 Center Post  
Set 1/2" 1. Rod Cap #30081
- 1) North - 6.26; Fd. Conc. Mon.
- 2) NE - 92.81; Fd. P.K. Nail in W. Face Of Utility Pole
- 3) ENE 20.15; Set P.K. Nail In S.E. Face Utility Pole
- 4) East - 33.08; Cut "4" @ B/C At Curb Cut.
- B-9 S. 1/4 Cor.  
Fd. P.K. Nail
- 1) East - 1.63; Fd. 1. Rod in Mon. Box.
- 2) S.35°E - 75.38; N.E. Cor. Conc. Block Foundation
- 3) South - 28.44; Nail & washer In W. side of 18" Maple
- 4) S.45°W. - 98.79; N.W. Cor. Conc. Block Foundation
- 5) N.80°W. - 71.65; Fd. P.K. Nail In S. Side of Utility Pole.  
(Previously Recorded in L. 2862, P. 854 (M.C.R.))
- A - 9 SW Sec. Cor.  
Fd. Railroad Spike
- 1) North - 44.58'; Fd. P.K. Nail In W. Side of Utility Pole.
- 2) S.55°E. - 67.97; Fd. Nail & Washer in N. Side of 12' Apple Tree
- 3) S.30°W. - 26.94; Nearest Face of Corner Metal Fe Post
- 4) N.50°E - 31.52; C/W of Fire Hydrant

Signed by Steven E. Dunn  
Surveyor's Michigan License No 28408

Date 5-15-1990

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 21, 1971  
REVISED MAY 18, 1973  
REVISED JAN., 1983

01575

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

1537503

RECORDED IN MACOMB COUNTY  
RECORDS AT: 11:0A. M.

JAN 11 1991

*Edna Hill*

CLERK - REGISTER OF DEEDS  
MACOMB COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

For corners in

Macomb <small>(County)</small>	Located In:	Corner Code #
1. Public Land Survey	T <u>3N</u> R <u>14E</u>	<u>A-9</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

4. Lot No. \_\_\_\_\_ Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Frank J. DeDecker, in a field survey on November 21, 1990, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules theretofore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	13	14	15	16	17	18							
7													
8	19	20	21	22	23	24							
9													
10	25	26	27	28	29	30							
11													
12	31	32	33	34	35	36							
13													

Chesterfield Township

A. Description of original monument and accessories and/or subsequent restoration:

A-9 Set railroad spike  
N.00°05'W. 44.53', P.K. nail in west side of Power Pole  
S.55°15'E., 68.38, nail & tin in N. side of 12" apple tree  
S.26°53'W. 26.86', nearest face of corner of metal fence post  
Land corner recordation certificate, L.2862, P.854, Macomb Co. Records

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-9 Found railroad spike 1.5'± north of Q. 22 Mile Rd. from above witnesses



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-9 SW corner section 19, found railroad spike  
= Az., 6°, 44.53', P.K. in west face U.P.  
= Az., 57°, 73.35', P.K. w/SDA tag in NW face 24" tree  
= Az., 109°, 96.10', P.K. in SW face U.P.  
= Az., 227°, 106.10', NW corner of Hse.#24980

Signed by Frank J. DeDecker Date 12-21-90  
Surveyor's Michigan License No. #8386

